

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

screwdriver, you just want to determine that the system will not unlock without the use of the proper tool.) Record results.

4. For the final check unlock the ISS system using the ISS tool and make sure the safety is in the "On Safe" position. Close and lockup the bolt on an empty chamber. Using the ISS tool attempt to lock the ISS system. Be careful, do not use excessive force or the ISS tool will be damaged. You should not be able to lock the ISS system with the bolt closed on a M710. Record results.

Data required:

- Rifle serial number
- Record results for all four phases of the ISS System function check.

TLW0407AT – Perform Bore Sighting Using Bushnell Scope:

Prior to the start of any live fire or accuracy testing a sample of the rifles will be inspected to determine if Mayfield has performed a bore sight check/adjustment after mounting the Bushnell Scopes. Use rifles A21-A30. Use standard Bore sighting procedures in the Long Range sighted in at 100 yards. One 5 shot group will be fired through each rifle to establish POI relative to POA. Note: Do not make any adjustment to the scope. They should be fired as received unless alignment of the scope to the bore is off considerably.

Data Required:

- Rifle serial number
- POI relative to POA for each rifle
- Review Results prior to further live fire testing of the test lot.

J.R.Snedeker

Page 19 of 32

10:47 AM

05/24/06

TLW0407

Remington Confidential

Revision # 2