

Phillip Reesor

From: Danner, Dale
Sent: 12/11/2000 11:07:31 AM
To: Reesor, Phillip K.
CC:
BCC:
Subject: FW: Interim M/710 Test Status -- Series C

From: Danner, Dale
Sent: Monday, December 11, 2000 11:04 AM
To: Golemboski, Matt R.; Bristol, II Ronald H.; Russo, Al; Keeney, Mike; Diaz, Danny; Franz, Scott; Snedeker, Jim
Subject: Interim M/710 Test Status -- Series C

Everyone,
Results of testing Dec. 10 as follows:

- 1) Drop testing -- All work is complete except Drop with the scope. Jar and Rotation passed in both configurations (with and without scope).
- 2) Box Bottoms -- 3 of 10 guns lost their bottoms during the 100 rnd test. Specifically, at round levels 49, 74, and 90. We have another 14 guns to put 100 rnds on so additional info will be available to base a go/nogo decision. (Marketing call)
- 3) Guns Swapped -- 2 guns were swapped in their boxes -- aka serial numbers on the box did not match the serial number on the gun. From a BATE point of view we have the correct guns based on the serial number list -- they did not however come in the correct box.
- 4) Boxes Difficult to Remove -- This continues to be a complaint by the technicians. Personally, I believe it to be a fairly low risk issue. May be related to box bottoms falling off due to increased force required to get the box out of the gun. (Marketing call)
- 5) Firing Pin Heads Loose - 12 of 30 guns had the firing pin head loose. Locktight issue?
- 6) Trigger Pull at Minimum - Several of the guns now have trigger pulls below process minimum (slightly). Average pull on 30 guns was 3.99 lbs. in the stock -- 4.17 lbs. out of the stock.

Dale

From: Danner, Dale
Sent: Thursday, November 30, 2000 10:50 AM
To: Golemboski, Matt R.
Cc: Bristol, II Ronald H.; Russo, Al; Keeney, Mike; Diaz, Danny; Franz, Scott; Snedeker, Jim
Subject: M/710 T&P Status Review - 11/27/00

Matt,
I thought it would be worthwhile to document our discussion/path forward on the various M/710 issues from our meeting on 11/27/00 as follows - please let me know if I've misstated your position:

- 1) Box Bottom Falling Off - I understand that we have potentially some 8000 box stampings in process of the current design. We will continue to use this level of design until stampings with the extended tab

Subject to Protective Order - Williams v. Remington