

Dale Danner

From: Franz, Scott  
 Sent: 11/06/2000 09:22:42 AM  
 To: Bristol, II Ronald H.; Golemboski, Matt R.; Diaz, Danny; Keeney, Mike  
 CC: Snedeker, Jim; Danner, Dale  
 BCC:  
 Subject: M/710 T & P Conference Call

Issues to discuss at the 10:00 a.m. meeting:

- \* Visual Inspection Issues as identified by John Trull
  - 1. ISS Keys missing - (3 of 30)
  - 2. Stock Sink - Left side
    - \* 1 of 30 unacceptable (measured .050" sink)
    - \* Worst case sample identified (measured .042" sink)
  - 3. Hard Bolt Cycle (translation) - 1 of 30 unacceptable
    - \* Improved w/cycling
  - 4. Bolt Stop Detent - 1 of 30 loose
- \* Measurement/Function Issues
  - 1. Headspace - 1 of 30 won't close on E-town Min. plug.
  - 2. Fire Control Operation
    - \* 2 of 30 guns had follow down malfunctions (A-14 & A-26)
    - \* 1 of 30 inadvertently discharged (A-26)
  - 3. Bolt Stop Breakage - 1 of 30 during Preliminary measurements

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0002603

ETE00002302