

**Dale Danner**

---

**From:** Danner, Dale  
**Sent:** 11/02/2000 09:37:01 AM  
**To:** Bristol, II Ronald H.  
**CC:**  
**BCC:**  
**Subject:** FW: 10 Gun Test Summary

FYI - Short summary of 10 Gun post-DAT pre-T&P audit. . . . This test was run primarily to demonstrate solutions to DAT issues of hard bolt closing and bolt stop release issues. Neither issue in my opinion was adequately addressed by these guns.

Franz issued our plan for T&P yesterday and will issue a timeline for that plan today. Please let me know of any comments/concerns.  
Dale

>-----  
>From: Franz, Scott  
>Sent: Thursday, November 02, 2000 8:54 AM  
>To: Golemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim  
>Subject: 10 Gun Test Summary  
>Importance: High  
>  
>Attached are the summary results for the 10 gun test that was completed yesterday.  
>  
>Results can be summarized as follows:(see attached file for specifics)  
>  
>\* 2 Bolt Handle Braze Failures  
> 1. One handle failed at 107 rounds during live fire testing  
> 2. The second handle failed during the bolt plug abuse test  
>\* Trigger pulls not within Specification  
>\* Followers sticking in magazine boxes  
>\* Bolt stop detent Inconsistent  
>\* Bolt Closing Force High  
> 1. Improved over DAT (Could not measure accurately)  
> 2. High closing force related to extractor operation (2 guns)  
>  
>In addition our "albeit" limited test shows the new bolt plug design superior. Recommend T&P samples all have the new configuration. Call if you have any questions.  
>  
>Scott  
>  
>  
>

Subject to Protective Order - Williams v. Remington

**BARBER 5.30.06R0002373**

**ETE00002372**