

Dale Danner

From: Franz, Scott
Sent: 11/02/2000 08:54:23 AM
To: Golemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale;
Snedeker, Jim
CC:
BCC:
Subject: 10 Gun Test Summary

Attached are the summary results for the 10 gun test that was completed yesterday.

Results can be summarized as follows:(see attached file for specifics)

- * 2 Bolt Handle Braze Failures
 - 1. One handle failed at 107 rounds during live fire testing
 - 2. The second handle failed during the bolt plug abuse test
- * Trigger pulls not within Specification
- * Followers sticking in magazine boxes
- * Bolt stop detent Inconsistent
- * Bolt Closing Force High
 - 1. Improved over DAT (Could not measure accurately)
 - 2. High closing force related to extractor operation (2 guns)

In addition our "albeit" limited test shows the new bolt plug design superior. Recommend T&P samples all have the new configuration. Call if you have any questions.

Scott

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060004770

ETE00002384