

Dale Danner

From: Franz, Scott
Sent: 11/01/2000 03:17:55 PM
To: Danner, Dale
CC:
BCC:
Subject: M710 10 Gun Test Summary.xls

Dale,

Attached are the summary results for the 10 gun test.

In summary we have the following issues:

- * Bolt Handle Braze (2 of 10 failed during limited testing)
- * Trigger Pull not within Specification (not statistically capable)
- * Followers sticking in magazine boxes
- * Bolt Stop Detent Inconsistent
- * Bolt Closing Force High
 1. Improved over DAT (Could not measure accurately)
 2. High closing force related to extractor operation (2 guns)

In addition our "albeit" limited test shows the new bolt plug design superior. Recommend T&P samples all have the new configuration.

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060005032

ETE00002515