

Remington Law Enforcement Training

Instructors

Fred Supry
Lyle Wheelock *Jerry Beigh* *Ken Nickerson*
Todd Pearson *Jason Spradling*


Tools





Magazine Cap




Another Way







Components



Clean hole



Use drill close to the size of the hole

Using Detent Staking Tool



Start with light tapping of hammer


Proper stake



Disassemble -squeeze left latch




Reassemble - right then left




Components





Fore-end nut wrench




Fore-end removed










Magazine spring




Damaged muzzle




Bent sight




Bolt assembly




Disassembly



Retaining pin




Firing Pin Removal



Component of Bolt






Retracting spring


1. 2. 3.

1. 2. 3.


1. 2. 3.









Blocking plunger







Plunger^{old / now}





Nomenclature





Broken ejector tip




Ejector Spring



Adjusting barrel fit





After



Timing cuts








Shell on carrier




Feeding to chamber



SBC - STC




STC - adjustment



Silver Bullet



Carrier Assembly




Silver bullet - use




Disassembly & Re-assemble




Action bar lock spring




Lock forward







TPA - left




Fired – left side




Fired – right side



Connector – Sear reset




Connector – Sear engaged




Trigger/connector/sear/hammer




Firing pin blocked




Firing pin alignment




Locking block cut





Flex tab – rec. right






Slide






Flex-tab drawing



Drawing bolt front




Shell latches




staking



Holding device




Correctly staked




Done wrong






Carrier clearance




Stock bearing plate



Stock fit .005 clearance



Stock Bolt & Washers



Stocks

