

By Malfunction Code - Repairs performed in 160001 NY Facility

Frequency 1/1/04 to 9/30/04

Malfunction Code	M-176 Returned For Recall/Up date	M-238 Clean & Inspect	M-239 Replace Trigger Assembly	M-240 Bolt Lock Safety Modificati on
40-X	0	0	0	2
600	15	0	6	2
600 Mohawk	4	0	1	1
660	10	0	2	1
700	0	0	79	30
721	0	0	19	7
722	0	0	6	2
XP 100	3	0	0	0
Total	32	0	113	45
	17%	0%	59%	24%

Backlog

Model	Approval Hold	Parts Hold
700/721	4	0
600/660	1	0
XP-100	0	0

By Malfunction Code - Repairs performed by RARC's

Frequency 1/1/04 to 9/30/04

Malfunction Code	M-176 Returned For Recall/Up date	M-238 Clean & Inspect	M-239 Replace Trigger Assembly	M-240 Bolt Lock Safety Modificati on
40-X	0	0	0	1
600	94	0	59	38
600 Mohawk	7	0	6	5
660	30	0	17	12
700	25	0	65	982
721	9	0	17	99
722	2	0	11	50
XP 100	2	0	0	1
Total	169	0	175	1188
	11%	0%	11%	78%

**Grand
Total**

2
23
6
13
109
26
8
3
190

**Grand
Total**

1
191
18
59
1072
125
63
3
1532