

Hi, On my Remington Sendero 700 what is the correct wat to tighten the stock ...

Discussion Thread

Response (Laura)

6/21/2002 11:22:21 AM

Dear Mr. Malcevicz,
Thank you for your inquiry. To tighten the guard screws, we recommend starting with the rear guard screw and snugng that up, then move to the front guard screw and snug that one up. You can then go back and tighten these further. We do not recommend torquing them down too tight because you can damage the stock.

There is not a recall on this firearm. We have a Safety Modification Program on certain model bolt action rifles. However this does not apply to your firearm.

You can read more information regarding our firearms and our Safety Modification program through the front page of our website or the link below:

http://www.remington.com/safety_modification_program/remington_safety.htm

The safe use and performance of your firearm depends on correct assembly and routine maintenance, as well as adherence to the "10 Commandments of Firearm Safety." <http://www.remington.com/support/10comm.htm> It is critical that you familiarize yourself with the information in both the owners manual and safety booklet. Whether you are a veteran shooter with a collection of Remington firearms, or a first time shooter, take the time to review this important literature and be certain that you are practicing firearm safety!

If you have any questions, please feel free to contact us at 1-800-243-9700 or 1-877-387-6691.

Customer (John Malcevicz)

6/20/2002 9:36:44 AM

Hi,

On my Remington Sendero 700 what is the correct wat to tighten the stock screws to the receiver? what is the correct torque for the stock screws? I read that there was a problem with the trigger going off when the safety was taken off.. Any recall on these rifles? Is my trigger safe?

Thank You
John Malcevicz