

I own a Mohawk-600, sn 6895xxx in 6MM. Rem. caliber. It has the original gold...

Discussion Thread

Response (Laura)

7/22/2002 11:12:25 AM

Dear Mr. Schmitz,
Thank you for your inquiry. According to the information provided, your firearm is included in the Model 600 recall. We recommend that you do not use the firearm and that you send it to a Remington Authorized Repair Center or our factory. You can read more information regarding this recall as well as instructions for sending it in through the front page of our website or the link below:

http://www.remington.com/safety_modification_program/remington_safety.htm

The safe use and performance of your firearm depends on correct assembly and routine maintenance, as well as adherence to the "10 Commandments of Firearm Safety." <http://www.remington.com/support/10comm.htm> It is critical that you familiarize yourself with the information in both the owners manual and safety booklet. Whether you are a veteran shooter with a collection of Remington firearms, or a first time shooter, take the time to review this important literature and be certain that you are practicing firearm safety!

If you have any questions, please feel free to contact us at 1-800-243-9700 or 1-877-387-6691.

Customer (C. E. Schmitz)

7/21/2002 1:41:34 PM

I own a Mohawk-600, sn 6895xxx in 6MM. Rem. caliber. It has the original gold plated trigger with vertical grooves. I have heard that there is a safety recall on this trigger assembly and would like to know exactly what the problem is and how to check for it. Also, If I have the problem, I will need instructions on how to get it fixed.