

If I have a remington 660 with a "v" stamped on the trigger under the
recieve...

Discussion Thread

Response (Jessica)
Dear Mark,

11/27/2002 9:26:50 AM

Thank you for your inquiry. The "v" does indicate that the trigger
assembly was replaced under the recall. Please click on the link below
for further information:

http://www.remington.com/Safety_Modification_Program/600_660.htm

Customer (Mark Donchek)

11/26/2002 9:48:26 AM

If I have a remington 660 with a "v" stamped on the trigger under the
reciever then does this mean that I DO NOT need any repairs regarding the
1979 recall of this model? Thank you.