

I have recently read some older reports (1993) of "the dropping of the strike...

Discussion Thread

Response (Chris)
Dear Mr. Shaw,

3/20/2003 3:07:21 PM

Thank you for contacting Remington Country. If you will forward the serial number for your Model 700 we will check to see if it has ever been involved in a recall. We would definitely want to inspect any firearm found to have such a problem.

Your rifle may have been originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Clay Shaw)

3/17/2003 10:43:23 PM

I have recently read some older reports (1993) of "the dropping of the striker in the Remington action when the safety was eased off." Since I have never heard of this before nor experienced it myself, I was hoping that you could shed some light on this.