

Model 700 Safety Switch Danger

Discussion Thread

Response (Chris)
Dear Mr. Petrone,

11/20/2003 10:46:01 AM

According to the serial number, your Model 700 was produced in 1988. It has not been involved in a recall.

If you would like it inspected or cleaned thoroughly, if in the US, we recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Bolsa Gunsmithing
7404 Bolsa Ave.
Westminster, CA 92683
Phone: 714-894-9100
Fax: 714-898-9164

Allison & Carey Gun Works, Inc.
17311 SE Stark
Portland, OR 97233
Phone: 503-256-5166

Sportsman's Haven, Inc.
14695 East Pike Rd.
Cambridge, OH 43725
Phone: 740-432-7243
Fax: 740-432-3204

Mann & Son Sporting Goods
515 W Water St.
Pinckneyville, IL 62274
Phone: 618-357-2911
Fax: 618-357-3658

Ahlman's, Inc.
9525 W. 230th Street
Morristown, MN 55052
Phone: 507-685-4244
Fax: 507-685-4280
<http://www.ahlmans.com/>

Sports World, Inc.
5800 S. Lewis Ave. Suite 154
Tulsa, OK 74105
Phone: 918-742-4027
Fax: 918-72-3981

Paducah Shooters Supply, Inc.
3919 Cairo St.
Paducah, KY 42001
Phone: 270-442-3242
Fax: 270-442-5022

Williams Gun Sight & Outfitters
7389 Lapeer Rd., Route #1
P.O. Box 329
Davidson, MI 48423
Phone: 810-653-2131
Fax: 810-658-2140

CONFIDENTIAL

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (David Petrone)

11/15/2003 1:03:37 PM

>

I'm sorry, I mis-entered the serial # for my rifle. The correct # is C6313018.

Again, it is a Model 700 7mm Mag.

It does not have the factory installed bolt lock and it is the B model which

can be unloaded from underneath the magazine.

Thank you.

David Petrone

This email has been scanned for viruses by McAfee Webshield e500 virus scanner.