

The Remington Model 788?

Discussion Thread

Response (Dell)

11/21/2003 5:33:30 PM

Dear Justin,

Thank you for your inquiry. The Model 788 does not qualify for the safety modification because of the way the bolt & safety are made. It cannot be updated.

You may wish to have a Remington Repair Center evaluate the firearm. Below is the one that services your state.

Jack First, Inc.
1201 Turbine Drive
Rapid City, SD 57703
Phone: 605-343-8481
Fax: 605-343-9420

Customer (Justin Monson)

11/17/2003 10:24:35 PM

Why wouldn't the Remington Model 788 be considered in the safety remodifications? I am from South Dakota and we just started our deer season. My dad had an unfortunate accident with his gun. He also has to put his gun on fire to take a shell out of the chamber. I think that is an unsafe step to take while taking out a bullet. His gun went off inside our pickup. We have the most respect for guns in our family. This was an unfortunate accident. I want to make sure this does not happen again. Luckily it did not hit anybody or hurt the vehicle. I just don't understand why this modification does not include this type of gun. Can I have this fixed? Why wouldn't it be free if it were a recall?

Thank You For Your Time,

A Concerned Sportsman