

Failure of 700 to cock on opening

Discussion Thread

Response (Jessica)
Dear Brian,

11/21/2003 5:28:37 PM

We apologize for any inconvenience you may be experiencing with your Model 700. If in the US, we recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Bolsa Gunsmithing
7404 Bolsa Ave.
Westminster, CA 92683
Phone: 714-894-9100
Fax: 714-898-9164

Allison & Carey Gun Works, Inc.
17311 SE Stark
Portland, OR 97233
Phone: 503-256-5166

Sportsman's Haven, Inc.
14695 East Pike Rd.
Cambridge, OH 43725
Phone: 740-432-7243
Fax: 740-432-3204

Mann & Son Sporting Goods
515 W Water St.
Pinckneyville, IL 62274
Phone: 618-357-2911
Fax: 618-357-3658

Ahlman's, Inc.
9525 W. 230th Street
Morristown, MN 55052
Phone: 507-685-4244
Fax: 507-685-4280
<http://www.ahlmans.com/>

Sports World, Inc.
5800 S. Lewis Ave. Suite 154
Tulsa, OK 74105
Phone: 918-742-4027
Fax: 918-72-3981

Paducah Shooters Supply, Inc.
3919 Cairo St.
Paducah, KY 42001
Phone: 270-442-3242
Fax: 270-442-5022

Williams Gun Sight & Outfitters
7389 Lapeer Rd., Route #1
P.O. Box 329
Davidson, MI 48423
Phone: 810-653-2131
Fax: 810-658-2140

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (Brian Henderson)

11/19/2003 8:32:19 PM

I have a Model 700 (serial number S6223196) which sometimes will not cock on opening. Even when opened and fully cycled with a new round, the firing pin does not stay cocked. It will eventually, but it sometimes takes several cycles of the bolt. The result is that the firing pin is not held all the way back and I am concerned that if not fully cocked it will result in a accidental discharge if the uncocked bolt is closed on a live round. Please let me know what I should do or if there was any kind of recall regarding this problem with this firearm.

Brian Henderson
P.O. Box 70
Stigler, OK 74462
(918) 967-8002