

remington model 600 30-06 cal

Discussion Thread

Response (Chris)  
Dear Mr. Tumolo,

3/23/2004 2:26:35 PM

Thank you for contacting Remington Country. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation. If it was produced before 1975 and has not been inspected, the trigger may need replacing. If it has already had the update it will have a "V" stamped on the trigger.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

Customer (eugene tumolo)

3/21/2004 1:40:38 PM

I recently was given a model 600 30-06 cal rifle which i have learned was the subject of a recall. could you provide information regarding all recalls for this rifle,, and the names of authorized gun dealers in new york state who would be able to preform the necessary repairs.

I would also appreciate information regarding mohawk model remington center fire rifles, and would appreciate information regarding this rifle such as the years of manufacture, calibres offered, various grades and wheather any of these rifles were effected by any recalls. thank you