

300 ultra 700 sendero has broken two seers in 130 rounds. why?

Discussion Thread

Response (Chris)

8/17/2004 3:30:28 PM

Dear Mr. Griffiths,

I spoke with you this afternoon regarding your Model 700. You can reach me at 800-243-9700, ext 8705 if you need further assistance.

Customer (James Griffiths)

8/13/2004 10:57:05 PM

each time the seer broke with no warning! The rifle discharged the first time, as I was closing the bolt. Almost making my friend and myself deph. As a result of this malfunction I had the rifle (which is less than 2 years old) repaired by my local gunsmith. (TJ gunsmithing)Thinking this accuracy was only a farce. He replaced the damaged seer with a Ed Brown Stainless Steel seer. Then today, (less than 1 month after the first seer broke)while rotating from safe to fire the rifle discharged again, sending a round wildly off target. Now sometimes the rifle fires as bolt is being closed or as safe is moved from safe to fire. Please help me solve this problem rite away before I lose all confidence in this rifle.

P.S. The following modafacations have been made to this rifle. 1= Kick ees pad , mosal brake, ziess scope and rings, trigger ajustment 3 1/2 lds

Thanks James Griffiths 3648 S. Laredo St #E Aurora CO 80013