

.375 H/H Remington rifle

Discussion Thread

Response (Chris)
Dear Mr. Lotz,

5/23/2005 11:11:01 AM

Remington bolt action rifles produced after 1982 did not have a bolt lock. The bolt could be opened and the firearm unloaded without having to put in on fire.

This is a mechanical product and should be inspected to ensure that it has not been improperly altered and all parts are not worn or unsafe.

Customer (Xagene Lotz)

5/17/2005 12:17:57 PM

Thank you, Chris for your prompt reply. I need some more info: was the firing mechanism of the rifles

after 1982 altered or improved? would you say that there is no way that this rifle will fire without warning, or

when the safety is operated? This is a fantastic rifle in looks, I just want to make sure of all the safety facts

before I buy it. Thanx, Xagene, South Africa