

service bulletin (recall)

Discussion Thread

Response (Chris)  
Dear Mr. Campbell,

12/13/2005 4:08:17 PM

Thank you for your patience. Your Model 600 was produced in 1975 and should be inspected for a trigger recall if you do not see a "v" stamped on the trigger. The "v" signifies we have already inspected it for the trigger recall.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Jennifer Campbell)

12/7/2005 7:48:24 PM

I have a 6mm, 600 Hohawk, ser#6807144. To my understanding in the 70's or early 80's there was a recall on the safety or trigger on the gun. What do I need to do for this gun? And does this gun fall under that recall? This gun has discharged when I have taken the safety off!