700 - triggers

Discussion Thread

Response (Kati) Dear Chris: 2/15/2006 11:20:35 AM

Thanks for visiting Remington Country! We appreciate your interest and support of Remington products. Please review attached:

Safety Modification Program

Remington Model 700 & Model 40-X
If you own a Remington Model 700 or Model 40-X rifle:
Only those Model 700 or 40-X rifles made before March 1982 were
manufactured with a bolt-lock mechanism. Model 700 or 40-X rifles made
after March 1982 do not have a bolt-lock mechanism and may be loaded and
unloaded with the safety in the "S" or "on Safe" position. Consequently,
post-1982 Model 700 or 40-X rifles are not subject to this bolt-lock
Safety Modification Program.
To determine whether your Model 700 or 40-X rifle has a bolt-lock
mechanism, either:

• Call Remington toll-free at 1-877-387-6691 and a service representative will help you determine if your fixearm has a bolt-lock mechanism, or • Take your Model 700 or 40-X rifle to a Remington Authorized Repair Center and a qualified gunsmith will examine your firearm and determine whether it has a bolt-lock mechanism.

If your Model 700 or 40-x rifle has a bolt-lock mechanism, it is eligible for this bolt-lock safety Modification Program. If you participate, your firearm will be cleaned and inspected for proper functioning by a qualified gunsmith. Once the condition of your firearm has been assessed, you will be notified of one of the following:

• Your firearm's trigger assembly is otherwise in good operating condition, and the gunsmit will proceed to physically remove the bolt-lock feature so that your rifle can be loaded and unloaded while the safety remains in the "\$ or "On Safe" position; or • Your rifle's trigger assembly is found to be in an unsatisfactory or potentially unsafe operating condition because of any number of factors, including wear, alteration or maintenance. The entire trigger assembly will be replaced with a new factory trigger assembly, which does not incorporate a bolt-lock mechanism.

In either case, the total cost to you is \$20, shipping and handling. You will also receive a safety redemption certificate to complete and submit in order to receive a free blaze orange hat (one hat per certificate).

How to participate in the Safety Modification Program

Complete the General Repair Form and Send or deliver your firearm and the completed repair form to either: a) A Remington Authorized Repair Center; or b) Ship your firearm to the Remington factory at: Remington Arms Company, Inc. Ilion Firearms Plant Attention: BL Safety Program 14 Hoefler Avenue Ilion, NY 13357

Remington will bill or arrange for payment once your firearm is received and evaluated.

CAUTION: It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm whether loaded in the firearm itself or included in the shipping container. The firearm should be transported only in a completely unloaded condition.

We appreciate the opportunity to be of service to you!

K. Howerton Consumer Services

Customer (Chris Noel) 2/15/2006 10:45:09 AM I have a 700 ADL which fired when I took the safety off scaring the shit out of me? Has others had similar problems with this?

