

ST	MODEL	SERIAL #	MFG. YR	COMPLAINT	REPAIR	GUNSHOP	TOTAL
MN	597	A2229793	02-81	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, ADJUSTED CLIP LATCH TO HOLD	20017	\$42.69
MN	597	2612572	04-97	M33	REPLACED HAMMER & TWO NEW MAGAZINES	20954	\$62.27
NY	597	2614537	05-97	M9	REPLACED EXTRACTOR & PLUNGER AND EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
IL	597	2621763	07-97	M24	REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$22.00
IL	597	2622793	07-97	M10, M29	REPLACED EJECTOR, EXTRACTOR & BOLT GUIDE RAILS AND TEST FIRED.	21028	\$32.83
CA	597	2618861	07-97	BOLT WILL NOT RELEASE	REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$36.00
IL	597	2621763	07-97	M24, M33	REPLACED MAG BOX AND TEST FIRED, REMOVED BURRS AT RIM AREA	21028	\$36.03
ARG	597	2624186	07-97		REPLACED MAG BOX ASSY, EXTRACTOR PLUNGER AND EXTRACTOR	104476	\$63.86
MN	597	2626157	08-97	M9	ADJUSTED EJECTOR, SMOOTHED ROUGH EDGES ON BOTTOM OF BOLT AND TEST	20017	\$46.94
MI	597	2628686	08-97	TRIGGER NOT FUNCTIONING.	REPLACED LINK PIN, STAKED HEAD OF PIN AND TEST FIRED.	20108	\$25.00
MD	597	2630934	08-97	BALL WON'T RETAIN EXTRACTOR, MOUTH OF CHAMBER DAMAGED	RETURNED TO FACTORY.	20021	\$10.00
MN	597	2639419	09-97	CLIP LATCH WON'T HOLD.	ADJUSTED EJECTOR AND TEST FIRED.	20017	\$39.40
SC	597	2637818	09-97	M9, M10	CLEANED CHAMBER, REPLACED MAGAZINE AND TEST FIRED.	21044	\$46.66
SC	597	2640308	09-97	MAGAZINE WILL NOT STAY IN GUN.	INSTALLED HOLD OPEN RETURN SPRING & FITTED MAGAZINE RELEASE RETAINING PIN	21044	\$22.40
GA	597	2637457	09-97	BAD EJECTION PROBLEM.	REPAIRED AS NECESSARY.	20300	\$45.00
SC	597	2632379	09-97	RETURN TO FACTORY.	RETURNED TO FACTORY.	20627	\$17.96
IL	597	2632075	09-97		TEST FIRED AND UPDATED.	21028	\$69.46
OH	597	2649115	10-97	EJECTOR PIN CAME OUT MISSING.	REPLACED EXTRACTOR, PLUNGER & SPRING, INSTALLED NEW TYPE EJECTOR,	21060	\$55.59

CT	597	2654663	11-97	M10, M23	REPLACED EXTRACTOR, PLUNGER & SPRING, CHECKED OVER, CLEANED & OILED, REPLACED TRIGGER ASSY & NEW TYPE	20629	\$47.55
OH	597	2656823	11-97	SAFETY & TRIGGER WON'T WORK.	EJECTOR, CLEANED, CHECKED AND TEST	21060	\$88.21
AL	597	2641341	12-97	M9	ADJUSTED EJECTOR.	21056	\$22.50
MN	597	2663762	12-97	M10	REPLACED EXTRACTOR, SPRING & PLUNGER AND TEST FIRED.	20017	\$47.95
CAN	597	2662376	12-97	DOES NOT PULL EMPTY SHELL OUT	REPLACED EXTRACTOR, SRING & FOLLOWER AND TEST FIRED.	20401	\$38.40
WI	597	2657827	12-97		REPLACED OLD EJECTOR AND MAGAZINE LATCH.	20616	\$16.59
MI	597	2666081	01-98	M9, M10	ADJUSTED EJECTOR, REPAIRED BOLT HOLD OPEN SPRING.	20108	\$42.00
OR	597	2667119	01-98	SHELLS WILL NOT EJECT PROPERLY.	INSTALLED NEW EJECTOR, EXTRACTOR & PLUNGER, CLEANED AND TESTED.	20023	\$45.18
FL	597	2664871	01-98	CHANGE OUT TO NEW EJECTOR.	INSTALLED NEW STYLE EJECTOR.	20030	\$17.23
MN	597	2666719	01-98	M5	REPLACED & FIT BROKEN BOLT HANDLE.	20017	\$30.57
CT	597	2664346	01-98	M9, M10, M23	REPLACED EXTRACTOR, PLUNGER, SPRING & MAGAZINE, CHECKED OVER, CLEANED &	20629	\$50.08
NC	597	2653361	01-98	TRIGGER WOULD NOT RESET ITSELF.	REPLACED TRIGGER ASSY.	21102	\$60.23
WI	597	2672166	02-98	M9	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21027	\$36.32
MD	597	2675633	02-98	WON'T FIRE.	REASSEMBLED & STAKED TRIGGER LINK, REINSTALLED PIN THAT HOLDS TRIGGER	20021	\$10.00
WI	597	2674014	02-98	WOULD NOT FIRE.	ASSY TO SEAR AND REINSTALLED SEAR	20616	\$35.00
MN	597	2673872	02-98	M23, M28	REPAIRED LINKAGE IN TRIGGER ASSY TO OPERATE SMOOTHLY, ADJUSTED EJECTOR	20017	\$47.27
CAN	597	2676522	02-98	M9	REPLACED BBL, REPROOFED, REFIT SIGHTS.	268418	\$95.07
NY	597	2671430	02-98	M10	REPLACED EXTRACTOR, PLUNGER & SPRING, FUNCTION & SAFETY CHECKED AND	21036	\$22.11
ARG	597	2672215	02-98		REPLACED FRONT SIGHT AND SCREW.	104476	\$60.73

OH	597	2671971	02-98	MISSING PARTS.	REPLACED MISSING SPRING, EJECTOR, EXTRACTOR, PLUNGER & SPRING, REPLACED RIVET, CLEANED & LUBRICATED, FUNCTION & SAFETY CHECKED AND TEST	21060	\$54.37
NY	597	2675839	02-98	FAILS TO FIRE.	EPOXIED LATCH PIN IN PLACE, REPLACED MAG LATCH, SPRING & PIN, CHECKED OVER, REPAIRED EJECTOR, ADJUSTED TRIGGER LINKAGE AND TEST FIRED.	21036	\$15.50
CT	597	2684271	03-98	M16, M23	ADJUSTED TRIGGER LINKAGE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	20629	\$50.61
MN	597	2678375	03-98	M9, M23	INSTALLED NEW STYLE EJECTOR. REPLACED BROKEN BOLT HANDLE SPRING & RIVET AND FIRING PIN, SAFETY & FUNCTION	20017	\$44.19
NY	597	2689520	04-98	M110	REPLACED EXTRACTOR, PLUNGER & SPRING AND TESTED	21177	\$20.00
GA	597	2688925	04-98	JAMS.		20502	\$12.31
NY	597	2684917	04-98	FAILS TO FIRE.		21036	\$37.64
LA	597	2684822	04-98	WOULD NOT EXTRACT.		21049	\$19.30
MN	597	2691222	04-98	M10	REPLACED EXTRACTOR. FOUND REAR MOUNT HAD BEEN LOWERED ALL THE WAY, ADJUSTED REAR SIGHT, POLISHED CHAMBER & DEBURRED.	20954	\$33.86
GA	597	2692439	05-98	ACCURACY.	CLEANED AND TEST FIRED.	20300	\$40.00
NE	597	2696124	05-98	M9, M23, M27	REPLACED EXTRACTOR, EJECTOR & SPRING.	21106	\$55.85
OR	597	2693709	05-98	BROKEN EXTRACTOR. SHOOTS INCORRECTLY, SOMETIMES SHOOTS AUTO	REPLACED TRIGGER HOUSING & MAGAZINE, CLEANED, CHECKED AND TEST FIRED.	20023	\$47.81
OH	597	2693559	05-98		REPLACED WEAK BOLT HANDLE, ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21060	\$94.18
MN	597	2692447	05-98	M5, M9	INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	20017	\$48.10
NY	597	2699794	06-98	M9		21177	\$20.00
OH	597	2698903	06-98	DOES NOT FIRE RIGHT, CHECK EVERYTHING, ACTION, FIRING PIN		21060	\$59.98
ARG	597	2699846	06-98		REPLACED FIRING PIN & SPRING. REPLACED MAGAZINE & EJECTOR, POLISHED & DEBURRED CHAMBER & BOLT.	104476	\$66.80
VT	597	2911843M	06-98	JAMS.		20803	\$116.71
MS	597	2699487	06-98	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00

OK	597	2707417	07-98		ADJUSTED BOLT HANDLE SPRING, SAFETY AND TEST FIRED.	21047	\$27.72
VA	597	2914263M	07-98	WON'T EXTRACT, PIECES OF MAG BLEW OUT.	REMOVED BOLT, REPLACED EXTRACTOR, PLUNGER & SPRING, REASSEMBLED.	20960	\$53.34
IL	597	2706040	07-98	M24, M29	REPLACED EJECTOR, EXTRACTOR, PLUNGER & SPRING AND TEST FIRED.	21028	\$25.77
NY	597	2916690M	08-98	M138	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	2700151	08-98	M25	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & REPLACED BOLTS & SCREWS, CHECKED	20629	\$49.53
CT	597	2654694	08-98	BED STOCK.	OVER, CLEANED & OILED, SAFETY & REPLACED EXTRACTOR, SPRING AND PLUNGER.	20629	\$43.93
VA	597	2711030	08-98	WON'T EXTRACT.	REPLACED OPERATING HANDLE SPRING & SPRING RIVET. INSTALLED NEW STYLE	20960	\$50.11
OK	597	2708309	08-98	M9		21047	\$36.32
IL	597	2916015M	08-98		REPLACED TRIGGER HOUSING ASSY.	21028	\$49.22
IL	597	2712239	09-98		METAL CLIP	21028	\$21.53
IL	597	2712239	09-98	M24, M33	REPLACED EJECTOR & MAG BOX. REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$39.86
NC	597	2918472M	10-98	M5	DRILLED OUT BOLT HANDLE RET SPRING & RIVET AND INSTALLED NEW ONE.	21102	\$38.20
AL	597	2918083M	10-98	M10	HONED CHAMBER.	21056	\$22.50
CAN	597	2918987M	10-98	CARTRIDGE JAMMING IN MAG, WILL NOT EXTRACT CART FROM	POLISHED CHAMBER, REPLACED DEFECTIVE MAG, TESTED, CLEANED AND OILED.	20630	\$34.65
VA	597	2717408	10-98	WON'T SHOOT STRAIGHT, SIGHTS WON'T ADJUST FAR ENOUGH.	REPLACED BBL, REAR SIGHTS & SCREWS AND TESTED.	20960	\$127.44
IA	597	2919564M	10-98	M10	REPLACED BROKE EXT.	20308	\$30.10
LA	597	2917347M	10-98	M9, M10, M23	REPLACED EXTRACTOR, SPRING & PLUNGER, REPLACED MAGAZINE AND	20204	\$40.65
IL	597	2917942M	10-98	M33	REPLACED MAGAZINE & HOLD OPEN RETURN SPRING AND TEST FIRED.	21028	\$48.30
CAN	597	2720906	11-98	ACCURACY PROBLEM.	INSTALLED NEW BBL, DRILLED & TAPPED HOLE ORIFICES AND TESTED AT RANGE.	21040	\$98.90

OK	597	271968B	11-98		INSTALLED OPERATING HANDLE CORRECTLY, INSTALLED NEW STYLE	21047	\$29.58
CAN	597	2921128M	11-98	M10	REPLACED BOLT HANDLE, MAG ASSY, EJECTOR, BOLT HANDLE SPRING, ACTION	21096	\$41.10
OR	597	2721406	11-98	MISSING EXTRACTOR.	REPLACED EXTRACTOR, CLEANED AND TESTED.	20023	\$28.52
LA	597	2722415	11-98	M5, M10	REPLACED EXTRACTOR, PLUNGER, RET SPRING & RIVET.	107416	\$32.92
OR	597	2721837	11-98	FIRE BULGING CASE.	RETURNED TO FACTORY.	20023	\$35.56
MN	597	2727776	12-98	M10	INSTALLED & FIT EXTRACTOR ASSY CORRECTLY, ADJUSTED BOLT HAMMER AND	20017	\$45.70
NY	597	2923803M	12-98	M145	REPLACED BOLT ASSY, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
IL	597	2724086	12-98	M24, M31, M33	REPLACED EJECTOR, MAG BOX & HOLD OPEN SPRING, REMOVED BURRS AT	21028	\$41.43
TX	597	2923169M	12-98	M9, M10	REPLACED EXTRACTOR, PLUNGER & SPRING, POLISHED CHAMBER, CLEANED &	21125	\$38.79
CO	597	2923480M	12-98	FAILS TO FIRE.	RETURNED TO FACTORY.	106412	\$15.00
MN	597	2729174	01-99	M23	ADJUSTED LINKAGE ON TRIGGER GROUP TO MOVE FREELY, ADJUSTED CLIP LATCH TO	20017	\$40.45
MN	597	2731959	01-99	M23	REPLACED CLIP, REPAIRED EJECTOR AND TEST FIRED.	20017	\$39.76
CAN	597	2924249M	01-99	RECEIVER CRACKED.	REPLACED RECEIVER, TRANSFERRED		
CA	597	2732167	01-99	SCOPE MT RAILS SCRATCHED. POOR FINISH ON RECEIVER, REC	PARTS & TESTED, TOOK OLD RECEIVER TO	20957	\$102.70
GA	597	2735921	02-99	JAMS.	SENT TO FACTORY.	20801	\$35.00
NY	597	2927035M	02-99	M145	INSTALLED NEW STYLE EJECTOR.	20502	\$12.31
OK	597	2741237	03-99	M9	REPLACED BROKEN BOLT ASSY, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NC	597	2742060	03-99	M5	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.58
VA	597	2748112	04-99	FAILS TO FULLY EXTRACT.	REPLACED BOLT HANDLE SPRING & RIVET.	21102	\$38.20
					INSTALLED NEW EJECTOR.	21090	\$30.17

OK	597	2745689	04-99	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$35.25
ARG	597	2747392	04-99		REPLACED BOLT, EXTRACTOR PLUNGER AND EXTRACTOR.	104476	\$119.10
OK	597	2747698	04-99		REPLACED TRIGGER HOUSING ASSY & 2 ISS KEYS, SAFETY & TEST FIRED.	21047	\$76.05
TX	597	2744522	04-99	BOLT BURNED A HOLE THRU IT.	SHIPPED GUN BACK TO CUSTOMER AFTER FULL INSPECTION SHOWED NO PROBLEMS.	21123	\$12.00
CT	597	2934333M	05-99	M23	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED. REPLACED MAG ASSY.	20629	\$48.79
KY	597	2750170	05-99	GUN JAMS.	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$16.00
IL	597	2749684	05-99	M10, M24	REMOVED BURRS AT CHAMBER, REPLACED EJECTOR AND TEST FIRED.	21028	\$25.16
IL	597	2750114	05-99	M10, M24	REPLACED EJECTOR, REMOVED BURRS AT CHAMBER AREA.	21028	\$33.56
CO	597	2749741	05-99	FAILS TO EXTRACT, JAMS & STOCK SCRATCHED ON FIRST RETURN.	SENT TO FACTORY.	106412	\$30.00
NY	597	2751455	06-99	M145	REPLACED BOLT HANDLE, BOLT SPRING & RIVET AND EJECTOR. SAFETY & FUNCTION	21177	\$20.00
MI	597	2751188	06-99	FIRE SHELL WITHOUT BEING CLOSED.	REPLACED EJECTOR, EXTRACTOR, PLUNGER AND SPRING.	21031	\$41.29
NY	597	2753537	06-99	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
IL	597	2755230	06-99		REPLACED TRIGGER HOUSING ASSY, EXTRACTOR & MAG CLIP.	21028	\$79.39
CO	597	2752646	06-99	M9	SENT TO FACTORY (SECOND TIME IN).	106412	\$30.00
NY	597	2937919M	07-99	M137	SAFETY & FUNCTION CHECKED AND TESTED, NO FAULT FOUND.	21177	\$20.00
TX	597	2937787M	07-99	EXTRACTOR ASSY MISSING.	REPLACED EXTRACTOR ASSY AND TEST FIRED.	21069	\$27.11
VA	597	2937104M	07-99	WON'T EXTRACT, LEAVES SHELL IN CHAMBER, EXTRACTOR MISSING.	REPLACED EXTRACTOR, SPRING AND PLUNGER.	20960	\$51.11
CA	597	2758888	08-99	EJECTION PROBLEMS.	INSTALLED EJECTOR UPGRADE.	20801	\$13.50
CT	597	2758142	08-99	M23	INSTALLED NEW EJECTOR & MAGAZINE, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$51.76

OK	597	2758918	08-99	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.58
KY	597	2759519	08-99	M23	REFIT MAG CATCHER, REPLACED MAGAZINE BOX ASSY.	20309	\$45.50
CT	597	2758124	08-99	M9, M10, M23, M29	REPLACED EJECTOR, EXTRACTOR, PLUNGER & SPRING, CHECKED OVER.	20629	\$47.78
IL	597	2758285	08-99	M24, M31	REPLACED EJECTOR, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$29.86
LA	597	2765947	09-99	M9	ADJUSTED EXTRACTOR, INCREASED TENSION ON EXTRACTOR SPRING, CLEANED	107416	\$36.00
OR	597	2766716	09-99	M9	FITTED EXTRACTOR HOOK, BENT EJECTOR UP & RIGHT, UNDERCUT RIGHT SIDE OF	21043	\$21.00
AL	597	2764606	09-99	M10	REPLACED EXTRACTOR SPRING, STRIPPED & EXAMINED, REFIT FRONT LINK	21056	\$24.10
NV	597	2943513M	09-99	WILL NOT FIRE.	OF TRIGGER PIN AND TESTED	80023	\$16.00
MI	597	2770376	10-99	M23, M33	FIT MAG LATCH TO GIVE MORE POSITIVE CATCH	20108	\$48.60
OH	597	2771848	10-99	SHELL GOT JAMMED IN CHAMBER.	INSTALLED EXTRACTOR, PLUNGER & SPRING AND MAG BOX ASSY, CLEANED, CHECKED	21060	\$61.56
MN	597	2944468M	10-99	SCOPE MOUNT HOLE STRIPPED OUT.	REDRILLED & TAPPED RECEIVER & REM BBL TO ACCEPT 8-40 SCREWS AND SUPPLIED	20017	\$50.84
OK	597	2768668	10-99	M9	REINSTALLED BOLT HANDLE & INSTALLED NEW STYLE EJECTOR, SAFETY & TEST	21047	\$34.46
TX	597	2770815	10-99	MAGAZINE WILL NOT STAY IN RIFLE.	REINSTALLED MAG CATCH SPRING & PIN, CHECKED OVER.	21017	\$17.50
TN	597	2944119M	10-99	BOLT HANDLE WILL NOT STAY IN BOLT.	REPAIRED LOOSE BOLT HANDLE RETAINER & MADE & FIT NEW RETAINER RIVET AND	21052	\$20.60
MI	597	2943634M	10-99	HANDLE FOR BOLT FALLS OUT.	REPLACED BOLT.	21030	\$109.81
MI	597	2768457	10-99	M10	REPLACED BROKEN EJECTOR AND TESTED.	20108	\$42.16
IL	597	2770148	10-99		REPLACED EJECTOR & MAGAZINE LATCH AND TEST FIRED.	21028	\$35.49
CT	597	2775073	11-99	M9, M23	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED, INSTALLED EJECTOR.	20629	\$41.95
OR	597	2775518	11-99	BROKEN SAFETY.	INSTALLED NEW EJECTOR, CHECKED SAFETY.	20023	\$37.93

OK	597	2775118	11-99	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
UT	597	2772928	11-99	BURR AT CHAMBER MOUTH.	POLISHED OFF BURR AND TEST FIRED.	107415	\$11.50
NY	597	2774871	11-99	M142	PERFORMED SAFETY & FUNCTION TESTS. REASSEMBLED MAG LATCH, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
KY	597	2774437	11-99	M23	REPAIRD MAG LATCH ASSY AND TESTED.	20309	\$21.50
NY	597	2773555	11-99	M137	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
WI	597	2772835	11-99	M9	REPLACED EJECTOR.	20616	\$15.17
IL	597	2775129	11-99	M15, M24, M33	REPLACED MAG BOX, LATCH & EJECTOR.	21028	\$54.82
MI	597	2775561	11-99		REPLACED TRIGGER ASSY AND TEST FIRED.	21054	\$52.99
OH	597	2775227	11-99	CLIP WON'T STAY IN.	REPLACED TRIGGER ASSY, CLEANED, CHECKED AND TEST FIRED	21060	\$80.48
VA	597	2775513	11-99	WON'T EXTRACT, MAG WON'T STAY TOGETHER, MAG LATCH BROKE.	REPLACED TRIGGER ASSY, EXTRACTOR & SPRING AND MAGAZINE.	20960	\$116.24
VA	597	2775521	11-99	T SAFETY STUCK, BUFFER CAME OUT OF ASSY, LOCKED UP GUN.	REPLACED TRIGGER ASSY, REINSTALLED BUFFER.	20960	\$79.49
CO	597	2773555	11-99	M23	RETURNED TO FACTORY, TEST FIRED WHEN BACK.	106412	\$18.00
CO	597	2775050	11-99	MAG WON'T STAY IN GUN.	RETURNED TO FACTORY.	106412	\$15.00
CO	597	2772529	11-99	FAILS TO FEED.	RETURNED TO FACTORY.	106412	\$15.00
NY	597	2775856	12-99	M110	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	2945286M	12-99	M137	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
AL	597	2775633	12-99	JAMS.	ADJUSTED EJECTOR.	21056	\$22.00
OH	597	2946959M	12-99	JAMS.	CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75
OH	597	2946961M	12-99	CLEAN AND CHECK.	CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75

MN	597	2944392M	12-99	M9, M10	DEGREASED EXTRACTOR SPRING & PLUNGER, ADJUSTED EXTRACTOR TO GRAB	20017	\$44.76
OH	597	2945341M	12-99	GUN JAMS.	INSTALLED EXTRACTOR, SPRING & PLUNGER, CLEANED, CHECKED AND TEST	21060	\$49.36
NY	597	2943741M	12-99	M993	REASSEMBLED CORRECTLY, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
MN	597	2944392M	12-99	DEFECTIVE MAG.	REPLACED DEFECTIVE MAGAZINE AND TEST FIRED.	20017	\$35.63
IL	597	2778869	01-00	M24, M31, M33	REPLACED EJECTOR, MAG BOX, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$41.86
TX	597	2777906	01-00	M9	REPLACED EJECTOR.	21123	\$20.67
AL	597	2777333	01-00	MAG LATCH FELL OUT.	REPLACED MAG LATCH.	21056	\$22.00
MI	597	2777268	01-00	CLIP DOESN'T HOLD.	REPLACED PIN AND SPRING ASSY IN REC.	21030	\$20.00
OH	597	2777240	01-00	CLIP KEEPS FALLING OUT.	REPLACED TRIGGER HOUSING, REPLACED NEW STYLE EJECTOR & ADJUSTED,	21060	\$0.00
NY	597	2950482M	01-00	M110	TIGHTENED TRIGGER LINKAGE RIVET, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
NY	597	2782855	02-00	M110, M137	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
OH	597	2782270	02-00	WILL NOT EJECT SHELLS.	GROUND EJECTOR FOR BOLT CLEARANCE, INSTALLED NEW TYPE OF EJECTOR.	21060	\$53.48
CT	597	2720413	02-00	M22	REPAIRED DING IN STOCK, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$41.25
CT	597	2720413	02-00	DEFECTIVE TRIGGER ASSY.	REPLACED DEFECTIVE TRIGGER ASSY, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$74.79
NY	597	2730801	02-00	M137	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
CT	597	2746205	02-00	M9, M23	REPLACED EJECTOR, CLEANED & POLISHED CHAMBER, CHECKED OVER, CLEANED &	20629	\$42.98
OK	597	2951604M	02-00		REPLACED TRIGGER HOUSING ASSY & LIFTERS, SAFETY & TEST FIRED.	21047	\$68.64
OK	597	2782034	02-00	M9	REPLACED TRIGGER HOUSING ASSY, INSTALLED NEW STYLE EJECTOR, SAFETY &	21047	\$68.81
WI	597	2783828	03-00	ROUNDS HANG UP, FEEDING PROBLEMS, JAMS.	CHECKED OVER ACTION, OILED, TEST FIRED, REPLACED MAGAZINE.	21024	\$25.79

LA	597	2783702	03-00	M23	CLEANED, TEST FIRED AND REPLACED MAGAZINE.	20204	\$26.25
CT	597	2784871	03-00	M9, M10, M23	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$42.98
CAN	597	2755831	03-00	NOT EJECTING SPENT OR LIVE RDS, NOT CYCLING PROPERLY,	INSTALLED NEW EJECTOR & MAG BOX,	21040	\$73.90
CAN	597	2954933M	03-00	BOLT JAMMING, NOT EXTRACTING AMMO.	ADJUSTED GUIDE ROD & SPRINGS, POLISHED CHAMBER, REPLACED	20630	\$41.08
VA	597	2783343	03-00	EXTRACTOR WON'T EXTRACT, EXTRACTOR MISSING.	EXTRACTOR, BOLT GUIDE RAILS AND REPAIRED MAG NOTCH TO ALLOW LOCKING	20960	\$47.74
MN	597	2953773M	03-00	M5	IN POSITION, REPLACED REAR SIGHT SLIDE REPLACED & FIT NEW BOLT RETAINING PIN	20017	\$48.23
CT	597	2784813	03-00		SPRING, ADJUSTED EJECTOR TO CATCH REPLACED EJECTOR, POLISHED CHAMBER	20629	\$42.98
WI	597	2783991	03-00	ROUNDS HANG UP, FAILS TO FEED, JAMS.	AREA, CHECKED OVER, CLEANED & OILED,	21024	\$25.79
CAN	597	2755629	03-00	M9, M10, M23	REPLACED MAG ASSY, REPLACED MAGAZINE, EJECTOR &	268418	\$45.23
FL	597	2953051M	03-00	SPRING HOLDING BOLT HANDLE BROKEN CAUSING OPERATING	EXTRACTOR, REBUILT AND TESTED.	20030	\$27.15
MI	597	2956173M	04-00	M5	SENT TO FACTORY. INSTALLED NEW BOLT HANDLE, CLEANED,	21019	\$30.95
OK	597	2787266	04-00	M9	CHECKED OUT AND TEST FIRED INSTALLED NEW STYLE EJECTOR, SAFETY &	21047	\$34.95
OK	597	2788081	04-00	M9	TEST FIRED. INSTALLED NEW STYLE EJECTOR, SAFETY	21047	\$29.46
MN	597	2788231	04-00	M23	AND TEST FIRED. POLISHED CHAMBER, ADJUSTED EJECTOR,	20017	\$47.13
OK	597	2786897	04-00	M9, M23	BOLT & HAMMER FROM BINDING AND TEST REPLACED ACTION SPRINGS, INSTALLED	21047	\$38.44
CT	597	2756371	04-00	M9, M23	NEW STYLE EJECTOR, SAFETY & TEST REPLACED EJECTOR, POLISHED CHAMBER,	20629	\$42.98
NY	597	2787412	04-00	M138	CHECKED OVER, CLEANED & OILED, SAFETY REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
CT	597	2715407	04-00	M23, M33	CHECKED AND TESTED, ADJUSTED ACTION REPLACED MAGAZINE, EXTRACTOR, SPRING	20629	\$50.08
NY	597	2956350M	04-00	M179	AND PLUNGER. REPLACED MISSING EXTRACTOR, PLUNGER	21177	\$20.00
					& SPRING, SAFETY & FUNCTION CHECKED		

CT	597	2787327	04-00	M8	REPLACED OPERATING HANDLE, SPRING & RIVET, CHECKED OVER, CLEANED & OILED, REPLACED STK ASSY, INSTALLED NEW	20629	\$47.49
OH	597	2786592	04-00	BROKEN STOCK.	STYLE EJECTOR & REPLACED REAR SIGHT, ADJUSTED EJECTOR TO ENGAGE SHELLS	21060	\$86.49
MN	597	2790566	05-00	M23	DEEPER, ADJUSTED CLIP LATCH SPRING	20017	\$41.51
OK	597	2786870	05-00	M1, M9	ADJUSTED EJECTOR, TIGHTENED LOOSE SIGHT, BORESIGHTED, SAFETY & TEST	21047	\$27.35
AL	597	2789191	05-00	M9	ADJUSTED EJECTOR.	21056	\$22.50
TX	597	2790318	05-00	DEFECTIVE.	CHECKED OVERALL, REPLACED BROKEN BUTT PLATE, TESTED FOR FEED AND	21087	\$36.19
CAN	597	2758132	05-00	RECEIVER CRACKED, INACCURATE.	INSTALLED NEW RECEIVER AND RANGE TESTED.	21040	\$73.18
CA	597	2791164	05-00	MAG WILL NOT STAY IN GUN.	REINSTALLED LATCH SPRING & REPLACED EJECTOR AND TEST FIRED.	20106	\$32.15
MN	597	2789992	05-00	SAFETY FUNCTION INCORRECT.	REPAIRED SAFETY & PLUNGER TO OPERATE SMOOTHLY AND TEST FIRED.	20017	\$43.38
ARG	597	2945069M	05-00		REPLACED BOLT HANDLE AND FIRING PIN.	104476	\$76.79
CAN	597	2732109	05-00	JAMMING.	REPLACED BROKEN EJECTOR, ADJUSTED AND TESTED.	20957	\$54.10
CAN	597	2750909	05-00	JAMMING, FIRING PIN NOT HITTING HARD.	REPLACED EJECTOR AND TESTED.	20957	\$53.60
CAN	597	2791654	05-00	M9, M23	REPLACED MAG BOX ASSY & HOLD OPEN RETURN SPRING AND TEST FIRED.	21096	\$73.39
ARG	597	2945071M	05-00		REPLACED MAG BOX ASSY AND FRONT SIGHT & SCREW.	104476	\$92.13
CAN	597	2783952	05-00	M23	REPLACED THREE MAGAZINES.	268418	\$42.63
CAN	597	2791532	05-00	SAFETY WOULD NOT ENGAGE.	REPLACED TRIGGER ASSY.	268418	\$45.66
MI	597	2790039	05-00		UPDATED TO NEW EJECTOR AND TEST FIRED.	21054	\$21.56
GA	597	2793154	06-00	M9	CLEANED UP GUMMED UP SUBSTANCE ON BUFFER BOLT, REINSTATED BUFFER AND	20300	\$50.00
CO	597	2795322	06-00	M23	FUNCTION CHECKED, ORDERED NEW MAGAZINE AND TEST FIRED.	106412	\$30.70

MI	597	2794651	06-00	M9	REPLACED EJECTOR AND TESTED.	20108	\$57.17
NY	597	2795587	06-00	M135	REPLACED TRIGGER HOUSING ASSY, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
NY	597	2784071	07-00	M138	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2612913	07-00	M110	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
OR	597	2798686	07-00	JAMS	INSTALLED NEW STYLE EJECTOR, TESTED AND CLEANED.	20023	\$40.28
OK	597	A2615051	08-00	M9	REPLACED BOLT SPRING RIVET, BOLT HANDLE SPRING & EJECTOR, SAFETY &	21047	\$31.20
NY	597	2960212M	08-00	M145	REPLACED BOLT SPRING, BOLT SPRING RIVET & BOLT HANDLE, SAFETY & FUNCTION	21177	\$20.00
OR	597	A2621688	09-00	MAG.	NOT STAYING OPEN ON EMPTY ADJUSTED MAG LATCH.	20023	\$18.00
SD	597	A2620378	09-00	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED	20510	\$25.91
OK	597	A2621890	09-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED	21047	\$18.73
OK	597	A2618999	09-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
MN	597	A2620562	09-00	FIRES WHEN SAFETY IS ON.	REPAIRED TRIGGER TO ENGAGE DEEPER AND TEST FIRED.	20017	\$41.40
CT	597	A2620116	09-00	M25	REPLACED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$42.98
AL	597	A2618075	09-00	M10	REPLACED EXTRACTOR AND PLUNGER.	21056	\$23.74
OK	597	A2621676	09-00	M9, M15	REPLACED MAG BOX ASSY, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$38.36
AL	597	A2621465	09-00	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
OR	597	A2618995	09-00	CARTRIDGE EXPLODED IN CHAMBER.	SENT TO FACTORY.	20023	\$25.56
ID	597	A2620989	09-00	FEED, EJECTION PROBLEMS, BOLT HANDLE POPS OUT.	TIGHTENED UP BOLT HANDLE, ADJUSTED EJECTOR FURTHER INTO BOLT FACE AND	20800	\$29.00
MS	597	A2615517	09-00	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00

AL	597	A2624722	10-00	M9	ADJUSTED EJECTOR.	21056	\$22.00
OR	597	A2623910	10-00	UPDATE EJECTOR.	CHECKED EJECTOR AND TESTED.	20023	\$29.36
SD	597	A2624741	10-00	M33	FUNCTIONS & SAFETY CHECKED, TEST FIRED. REPLACED MAGAZINE.	20510	\$32.47
SD	597	A2615215	10-00	SIGHT PART MISSING.	FUNCTIONS & SAFETY CHECKED, TEST FIRED. REPLACED REAR SIGHT ADJUSTURE	20510	\$30.50
AL	597	A2626550	10-00	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2626766	10-00	M10	HONED CHAMBER.	21056	\$22.50
IL	597	A2623168	10-00	M5	INSTALLED NEW SPRING & RIVET.	21028	\$23.86
OK	597	A2626087	10-00	M9	INSTALLED NEW STYLE EJECTOR, REPLACED SPRING, BOLT HANDLE & RIVET.	21047	\$31.20
OK	597	A2626756	10-00	M9	INSTALLED NEW STYLE EJECTOR, TEST FIRED AND SAFETY CHECKED	21047	\$35.96
AL	597	A2618148	10-00	M10	POLISHED CHAMBER.	21056	\$22.50
IL	597	A2625240	10-00	SIGHTS DRILLED OFF CENTER.	REPLACED BBL AND TEST FIRED	21028	\$64.06
GA	597	A2622818	10-00	NEEDS NEW HANDLE.	REPLACED BOLT HANDLE AND EJECTOR.	20502	\$21.84
CT	597	A2623971	10-00	M5	REPLACED BOLT HANDLE, SPRING & RIVET.	20629	\$48.93
NY	597	A2624315	10-00	M146	CHECKED OVER, CLEANED & OILED, SAFETY REPLACED BOLT SPRING, BOLT SPRING RIVET, REPLACED EJECTOR, SAFETY &	21177	\$20.00
IL	597	A2625782	10-00		REPLACED EJECTOR & MAG BOX, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$40.74
KY	597	A2624009	10-00	WON'T CYCLE OR EJECT.	REPLACED EJECTOR AND BOLT ASSY AND TEST FIRED.	21072	\$69.84
IL	597	A2625783	10-00		REPLACED EJECTOR AND MAG BOX, TEST FIRED.	21028	\$30.74
KY	597	A2624009	10-00	M9	REPLACED EJECTOR AND TEST FIRED.	21072	\$21.23
CAN	597	A2623054	10-00	M9	REPLACED EJECTOR AND TESTED.	268418	\$13.03

NY	597	A2617397	10-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2625649	10-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CAN	597	A2623208	10-00	M9	REPLACED EJECTOR.	268418	\$13.03
AL	597	A2625159	10-00	WON'T FIRE, FIRING PIN RETAINING PIN FELL OUT.	REPLACED FIRING PIN RETAINING PIN.	21056	\$24.10
VA	597	A2623424	10-00	BROKEN CLIP.	REPLACED MAG BOX ASSY.	21090	\$6.70
OK	597	A2617735	10-00	M9, M15, M23	REPLACED MAGAZINE, EJECTOR, EXTRACTOR, PLUNGER AND SPRING.	21047	\$44.56
OK	597	A2616124	10-00	M9	REPLACED MAGAZINE, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$41.28
OR	597	A2620280	10-00	SIGHT MISSING.	REPLACED MISSING SIGHT.	20023	\$34.05
OK	597	2799085	10-00	M9	REPLACED RIVET, SPRING & INSTALLED NEW STYLE EJECTOR, SAFETY & TEST	21047	\$32.77
OR	597	A2613880	10-00	M28	REPLACED TRIGGER HOUSING ASSY.	20200	\$68.07
CAN	597	A2623777	10-00	M9	REPLACED WITH N/S EJECTOR	268418	\$21.88
AL	597	A2615823	10-00	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
CAN	597	A2623223	10-00	M9	STRIPPED DOWN, EXCHANGED EJECTOR, REBUILT AND TESTED.	268418	\$13.03
OK	597	A2616242	10-00	M1	TIGHTENED LOOSE REAR SIGHT, ADJUSTED SIGHTS TO ALIGN WITH BORE.	21047	\$28.02
OK	597	A2615850	10-00	M1, M9	TIGHTENED LOOSE SIGHT, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OR	597	A2624645	10-00	GUN CLIP JAMS.	UPDATED EJECTOR, CLEANED AND TESTED.	20023	\$54.28
MS	597	A2620275	10-00	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
AL	597	A2628726	11-00	JAMS.	ADJUSTED EJECTOR.	21056	\$22.00
AL	597	A2628461	11-00	M9	ADJUSTED EJECTOR.	21056	\$22.50

MT	597	A2627343	11-00	M23	ADJUSTED FEEDING AND TEST FIRED.	20113	\$30.25
IL	597	A2627833	11-00	M19	BLUED BBL AND PUT BACK TOGETHER.	21028	\$35.00
LA	597	A2628974	11-00	M9, M23	CLEANED & POLISHED CHAMBER, ADJUSTED EJECTOR.	20204	\$26.25
OR	597	A2631157	11-00	MISFIRES.	CLEANED, UPDATED EJECTOR AND TESTED. FUNCTIONS & SAFETY CHECKED, TEST FIRED.	20023	\$43.67
SD	597	A2628736	11-00	M9		20510	\$25.70
AL	597	A2627133	11-00	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2628613	11-00	M10	HONED CHAMBER.	21056	\$22.50
KY	597	A2627833	11-00	NOT FEEDING OR EJECTING ALL THE TIME.	INSTALLED NEW STYLE EJECTOR & REPLACED MAG AND TEST FIRED.	21072	\$26.70
OK	597	A2631087	11-00	M1, M9	INSTALLED NEW STYLE EJECTOR, BORESIGHTED, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2627457	11-00	M9	INSTALLED NEW STYLE EJECTOR, REPLACED RIVET, BOLT SPRING & SPRING	21047	\$31.69
OK	597	A2628733	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$35.25
OK	597	A2630609	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.95
OK	597	A2628320	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2628556	11-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.53
MI	597	A2628379	11-00	JAMS.	POLISHED CHAMBER, INSTALLED NEW STYLE EJECTOR AND TESTED.	21030	\$22.23
CT	597	A2629916	11-00	M23	REAMED & POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$48.32
MN	597	A2629512	11-00	NOT FEEDING. EXTR ASSY MISSING, BOLT ASSY	REFIT EXTRACTOR AND TESTED.	20954	\$26.00
TN	597	A2630163	11-00	DEFECTIVE.	REPLACED BOLT & FIT NEW EXTRACTOR ASSY AND TEST FIRED.	21052	\$67.29
CA	597	A2630176	11-00	NOT EJECTING.	REPLACED BROKEN EJECTOR AND TEST FIRED.	20112	\$23.75

OK	597	A2631061	11-00	M9	REPLACED BROKEN TRIGGER HOUSING ASSY, INSTALLED NEW STYLE EJECTOR, REPLACED CLIP ASSY, REINSTALLED	21047	\$71.19
AL	597	A2627521	11-00		EXTRACTOR.	21056	\$30.78
OK	597	A2631085	11-00	M9	REPLACED DEFECTIVE FIRING PIN, INSTALLED NEW STYLE EJECTOR, SAFETY & REPLACED EJECTOR & REMOVED BURRS	21047	\$41.80
CA	597	A2630107	11-00	M23	FROM CHAMBER AND TEST FIRED.	20106	\$32.15
FL	597	A2628711	11-00	WON'T EJECT.	REPLACED EJECTOR WITH NEW STYLE AND TEST FIRED.	20603	\$14.70
NY	597	A2629802	11-00	M137	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2630319	11-00	M110	REPLACED EJECTOR, PLACED HOLD OPEN SPRING IN PROPER POSITION, SAFETY & REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NY	597	A2630840	11-00	M137	CHECKED AND TESTED.	21177	\$20.00
OK	597	A2628448	11-00	M9, M15, M23	REPLACED MAGAZINE & EJECTOR, SAFETY & TEST FIRED.	21047	\$38.73
IL	597	A2630909	11-00	M10, M33	REPLACED MAGAZINE AND EJECTOR.	21028	\$44.16
AL	597	A2629932	11-00	TRIGGER ASSY CRACKED CAUSING MALFUNCTION.	REPLACED TRIGGER ASSY.	21056	\$61.73
NY	597	A2633028	12-00	M137	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
MN	597	A2633014	12-00	M10	ADJUSTED TRIGGER GROUP TO OPERATE CORRECTLY, ADJUSTED EJECTOR TO	20017	\$51.47
MI	597	A2632898	12-00	JAMS.	CLEANED, POLISHED CHAMBER AND TESTED.	21030	\$34.95
OR	597	A2632282	12-00	WON'T FEED PROPERLY, JAMS.	CLEANED, UPDATED EJECTOR AND TESTED.	20023	\$39.84
NY	597	A2632820	12-00		FUNCTION TESTED, REPLACED EJECTOR.	20312	\$30.81
AL	597	A2631420	12-00	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2632367	12-00	M23	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$18.73
OK	597	A2632284	12-00	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58

AL	597	A2633053	12-00	M9	REPLACED EJECTOR AND TEST FIRED.	21026	\$33.65
NY	597	A2632505	12-00	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	A2632360	12-00	M9	REPLACED EJECTOR.	21047	\$18.73
AL	597	A2633408	01-01	JAMS.	ADJUSTED EJECTOR.	21056	\$22.50
AL	597	A2633688	01-01	JAMS.	ADJUSTED EJECTOR.	21056	\$22.00
AL	597	A2633425	01-01	JAMS.	ADJUSTED EJECTOR.	21056	\$22.50
OR	597	A2633564	01-01	ACTION WON'T LOCK OPEN. CLIP WON'T LOCK IN WITH AMMO	ADJUSTED HOLD OPEN LATCH.	20023	\$29.55
CAN	597	A2637475	01-01	M18	CHAMBER STOCK. CLEANED & OILED BBL, CHAMBER,	268418	\$18.65
MI	597	A2636387	01-01	M9, M10	REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17
NY	597	A2636817	01-01	M201	CLEANED DEBRIS FROM BOLT FACE, REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NC	597	A2633694	01-01	M5	DRILLED OUT BOLT HANDLE & RIVET AND INSTALLED NEW ONE.	21102	\$23.20
CAN	597	A2636350	01-01	M9, M23	EXCHANGED MAGAZINE, EJECTOR & FIRING AND TESTED.	268418	\$45.23
CAN	597	A2635387	01-01	M9, M10	FIT NEW EJECTOR & EXTRACTOR AND TESTED.	268418	\$13.82
SD	597	A2633534	01-01		FUNCTIONS & SAFETY CHECKED, TEST FIRED.	20510	\$25.60
SD	597	A2637899	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. ADJUSTED EXTRACTOR.	20510	\$30.70
SD	597	A2633606	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. ADJUSTED EXTRACTOR.	20510	\$30.80
SD	597	A2637899	01-01	M9	FUNCTIONS & SAFETY CHECKED, TEST FIRED. NO MALFUNCTIONS.	20510	\$27.60
OH	597	A2632231	01-01	REPEATEDLY JAMS UP.	GROUND EJECTOR, REPLACED CLIP & INSTALLED NEW EJECTOR PIN, CLEANED,	21060	\$59.18
OH	597	A2633609	01-01	JAMS SHELLS.	GROUND SIDE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$45.75

AL	597	A2636501	01-01	M10, M24	HONED CHAMBER.	21056	\$22.00
AL	597	A2637049	01-01	M10	HONED CHAMBER.	21056	\$22.50
OR	597	A2632264	01-01	BOLT LEVER BROKE.	INSTALLED BOLT HANDLE SPRING & RIVET, UPDATED WITH NEW STYLE EJECTOR AND	20023	\$33.23
KY	597	A2636408	01-01	ACTION SQUEAKS.	INSTALLED NEW EJECTOR AND TEST FIRED.	21072	\$26.23
KY	597	A2636814	01-01	JAMS.	INSTALLED NEW EJECTOR AND TEST FIRED.	21072	\$21.23
KY	597	A2636399	01-01	JAMS.	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$21.23
KY	597	A2636541	01-01	JAMS.	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21072	\$21.23
MI	597	A2635965	01-01	M9	INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21019	\$40.25
OH	597	A2633824	01-01	MISSING BOLT LEVER.	INSTALLED NEW STYLE EJECTOR, REPLACED BOLT ASSY & NEW BOLT	21060	\$91.07
OK	597	A2637742	01-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2635978	01-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$30.25
OH	597	A2635208	01-01	SHELL CASING GETS JAMMED WHEN EJECTED, ACTION DOESN'T	INSTALLED NEW TYPE OF EJECTOR CLEANED, CHECKED AND TEST FIRED.	21060	\$42.48
AL	597	A2637451	01-01	M23, M24	RECUT CHAMBER.	21056	\$22.50
AL	597	A2633396	01-01	M24	REMOVED BURR.	21056	\$22.50
AL	597	A2631731	01-01	M23, M24	REPLACED CLIP ASSY, REMOVED BURR FROM CHAMBER.	21056	\$31.28
MI	597	A2635848	01-01	M9	REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17
KY	597	A2636516	01-01	M9	REPLACED EJECTOR WITH NEW STYLE, CLEARED ACTION AND TEST FIRED.	21072	\$38.73
NY	597	A2636805	01-01	M137, M940	REPLACED EJECTOR, ADJUSTED HOLD OPEN, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
AL	597	A2637709	01-01	JAMS AFTER FIRING.	REPLACED EJECTOR.	21056	\$25.00

CAN	597	A2635075	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635380	01-01	M9	REPLACED EJECTOR.	268418	\$21.68
CAN	597	A2635366	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635267	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CAN	597	A2635021	01-01	M9	REPLACED EJECTOR.	268418	\$13.03
CT	597	A2636890	01-01	M9, M10, M23	REPLACED MAG, LATCH, SPRING & PIN, CLEANED AND OILED.	20629	\$50.61
CAN	597	A2635524	01-01	WON'T FEED PROPERLY, MISFIRES & STOVEPIPES.	REPLACED NEW STYLE EJECTOR AND MAGAZINE.	268418	\$44.44
OR	597	A2632264	01-01	MISSING SCREW ON TAP	REPLACED PLUG SCREW.	20023	\$30.33
AL	597	A2633714	01-01	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50
MN	597	A2642065	02-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND TEST FIRED.	20017	\$41.64
NY	597	A2638371	02-01	CAN'T PUT BOLT HANDLE IN GUN.	ADJUSTED OPERATING HANDLE BOLT SPRING, FUNCTION & SAFETY CHECKED AND	21036	\$24.00
CAN	597	A2639173	02-01	M9	EXCHANGED N/S EJECTOR.	268418	\$13.03
MI	597	A2636276	02-01	JAMS.	INSTALLED & ADJUSTED NEW EJECTOR.	21054	\$49.23
CT	597	A2638247	02-01	M16, M33	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$51.75
CT	597	A2638216	02-01	M25	INSTALLED MODIFIED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY &	20629	\$42.98
OK	597	A2641360	02-01	M1, M9	INSTALLED NEW STYLE EJECTOR, ADJUSTED SIGHTS TO ALIGN WITH BORE,	21047	\$29.58
NE	597	A2640484	02-01	M9	POLISHED CHAMBER, REPLACED MAGAZINE.	21106	\$60.88
TX	597	A2640180	02-01	WON'T FEED OR EJECT.	REFIT SEAR SPRING, INSTALLED EJECTOR AND TEST FIRED, CHECKED ALL FUNCTIONS	21087	\$24.03
NY	597	A2638371	02-01	M5	REPLACED BOLT HANDLE SPRING & RIVET BOLT SPRING & ACTION SPRING, SAFETY &	21036	\$22.43

IL	597	A2641210	02-01	M29, M33	REPLACED EJECTOR & MAG BOX AND TEST FIRED.	21028	\$49.70
NY	597	A2636346	02-01	M138	REPLACED EJECTOR, ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2637458	02-01	M138	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TEST FIRED.	21177	\$20.00
NY	597	A2639165	02-01	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2638027	02-01	M9	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	A2638277	02-01	M9, M10, M20, M23	REPLACED EXTRACTOR, SPRING & PLUNGER, REAR SIGHT ASSY & BASE,	20629	\$72.50
NC	597	A2640797	02-01	M23	REPLACED MAG ASSY, CHECKED EXTRACTOR AND TEST FIRED.	21102	\$40.78
CAN	597	A2636336	02-01	M9	STRIPPED DOWN, EXCHANGED EJECTOR, REBUILT AND TESTED.	268418	\$13.03
NY	597	A2645276	03-01	M137	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	A2644003	03-01	M110	ADJUSTED TRIGGER LINKAGE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
OH	597	A2643701	03-01	DIDN'T WANT.	CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75
OK	597	A2645020	03-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OH	597	A2644284	03-01	CHECK OVER AND RETURN.	INSTALLED NEW TYPE EJECTOR, GROUND EJECTOR FOR BOLT CLEARANCE, CLEANED,	21060	\$52.48
NY	597	A2645466	03-01	M110	REMOVED BURR FROM REAR OF CHAMBER, REPLACED EJECTOR, SAFETY & FUNCTION	21177	\$20.00
IL	597	A2644347	03-01	M24	REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$22.00
NY	597	A2644196	03-01	M145	REPLACED BOLT SPRING & RIVET, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2643816	03-01	M138	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TEST FIRED. ADJUSTED	21177	\$20.00
OK	597	A2644383	03-01		REPLACED MAG BOX ASSY, REINSTALLED EXTRACTOR, INSTALLED NEW STYLE	21047	\$41.36
NY	597	A2645909	04-01	M23	ADJUSTED ACTION TIGHTNESS, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00

NY	597	A2646176	04-01	M142	ADJUSTED MAGAZINE, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
TX	597	A2647351	04-01	DOES NOT EJECT/EXTRACT.	CHECKED EXTRACTOR, BBL, CHAMBER, TRIGGER ASSY, BOLT ASSY, MAGAZINE,	21087	\$38.52
AL	597	A2646157	04-01	M10	HONED CHAMBER.	21056	\$22.50
OH	597	A2647305	04-01	HALL EJECTOR & CLIP FELL APART.	INSTALLED BOLT ASSY & NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST	21060	\$81.09
FL	597	A2648224	04-01	M10	INSTALLED MISSING EXT, SPRING & PLUNGER AND TEST FIRED.	20624	\$41.30
OK	597	A2647565	04-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OR	597	A2648730	04-01	MISFIRES, JAMS.	INSTALLED NEW STYLE EJECTOR, TESTED AND CLEANED.	20023	\$40.55
OR	597	A2648770	04-01	JAMS.	INSTALLED NEW UPDATED EJECTOR AND TESTED.	20023	\$37.93
CT	597	A2648661	04-01	M23, M33	RELIEVED PORT FOR MAG & LATCH, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$47.44
MN	597	A2646669	04-01	M5	REPAIRED BOLT RETAINER TO HOLD BOLT HANDLE IN PLACE, INSTALLED NEW BOLT	20017	\$46.72
MI	597	A2645971	04-01	JAMS.	REPLACED BOLT ASSY & EJECTOR	21030	\$65.84
NY	597	A2648355	04-01	M114	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CAN	597	A2648265	04-01	DOES NOT FEED SHELLS FROM MAG.	REPLACED MAGAZINE, TESTED.	21046	\$20.50
NY	597	A2647172	04-01	M129	REPLACED MISSING EXTRACTOR, PLUNGER & SPRING AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
IA	597	A2645603	04-01	M9	TOP OF RECEIVER HAD A ROUGH SPOT.	20308	\$33.50
MN	597	A2649817	05-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, FREED UP STICKY LINKAGE IN	20017	\$48.01
MN	597	A2649862	05-01	M9	ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, SMOOTHED BOLT TRAVEL AND	20017	\$47.01
AL	597	A2651000	05-01	M9	ADJUSTED EJECTOR.	21056	\$22.50
OK	597	A2650793	05-01	M1, M9	ADJUSTED SIGHTS TO ALIGN WITH BORE, BORESIGHTED, INSTALLED NEW STYLE	21047	\$29.58

OH	597	A2650463	05-01	CHECK TO SEE IF OKAY.	GROUND EJECTOR FOR BOLT CLEARANCE, INSTALLED NEW TYPE OF EJECTOR,	21060	\$50.25
AL	597	A2650667	05-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2650798	05-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2649728	05-01	M9	INSTALLED NEW STYLE EJECTOR, DISENGAGED ISS SYSTEM, SAFETY & TEST	21047	\$29.95
OK	597	A2650926	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.46
OK	597	A2650822	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2650072	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2650530	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.46
OK	597	A2650981	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OH	597	A2651332	05-01	SHOOTS HIGH. CLIP COMES OUT WITHOUT	INSTALLED NEW TYPE EJECTOR, INLET STOCK PROPERLY, CLEANED, CHECKED AND	21060	\$56.75
OH	597	A2651240	05-01	HITTING THE RELEASE.	INSTALLED NEW TYPE OF EJECTOR.	21060	\$55.18
AL	597	A2650305	05-01	M10	REPLACED MAGAZINE, GROUND EDGE OF	21056	\$22.50
MN	597	A2649771	05-01	M8, M9	POLISHED CHAMBER.	21056	\$22.50
OH	597	A2650170	05-01	NOT ACCURATE.	REPAIRED TRIGGER LINKAGE TO OPERATE FREELY, ADJUSTED EJECTOR TO ENGAGE	20017	\$44.14
NY	597	A2652941	05-01	M145	REPLACED BOLT ASSY, INSTALLED NEW STYLE EJECTOR, CLEANED, CHECKED AND	21060	\$61.75
NY	597	A2650464	05-01	M9	REPLACED BOLT HANDLE, BOLT SPRING & RIVET AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NY	597	A2652037	05-01	M134	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	A2651199	05-01	M9, M23, M33	REPLACED MAG BOX, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND	21177	\$20.00
SC	597	A2651510	05-01	M33	REPLACED MAGAZINE & EXTRACTOR, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$48.32
					REPLACED MAGAZINE.	21044	\$18.78

OH	597	A2650138	05-01	NOTHING ON PAPERWORK.	REPLACED TRIGGER ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$99.48
OH	597	A2650160	06-01	TO BE CHECKED.	REPLACED TRIGGER HOUSING, CLEANED, CHECKED AND TEST FIRED.	21060	\$76.48
CO	597	A2652149	05-01	M9 MAGAZINE NOT STAYING IN RIFLE.	RETURNED TO FACTORY, THEN SENT BACK TO CUSTOMER.	106412	\$30.00
OR	597	A2650219	05-01	BULLETS NOT LOADING INTO RIFLE.	UPDATED EJECTOR, REFIT MAG LATCH. BEAD BLASTED BBL & BLUED, CLEANED, CHECKED AND TEST FIRED.	20023	\$43.82
OH	597	A2656739	06-01	RUSTED BBL.	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	21060	\$81.75
CT	597	A2655898	06-01	M25	CLEANED, OILED AND POLISHED CHAMBER, CHECKED OVER, SAFETY & FUNCTION	20629	\$40.75
CT	597	A2655856	06-01	M9, M10, M23, M33	CLEANED, REPLACED EJECTOR AND TESTED.	20629	\$50.03
OR	597	A2656025	06-01	JAMMING.	FUNCTIONS & SAFETY CHECKED, TEST FIRED, REPLACED MAGAZINE.	20023	\$46.24
SD	597	A2653350	06-01	MISFIRES.		20510	\$32.47
AL	597	A2655731	06-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2657258	06-01	M9	INSTALLED NEW STYLE EJECTOR, DEBURRED MAGAZINE LATCH, SAFETY & INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2657306	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2655923	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2654289	06-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2657036	06-01	M9	INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21047	\$18.73
OH	597	A2657270	06-01	BLEW UP ON CUSTOMER.	INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98
OH	597	A2656014	06-01	HANGING SHELLS.	REPLACED BOLT SPRING & RIVET, SAFETY & TEST FIRED.	21060	\$48.48
OK	597	A2654311	06-01	M23	REPLACED EJECTOR, POLISHED CHAMBER AND TEST FIRED.	21047	\$30.91
MI	597	A2653643	06-01	M9		20108	\$65.97

IL	597	A2653164	06-01	M33	REPLACED MAG BOX, TEST FIRED.	21028	\$32.98
OK	597	A2657297	06-01	M9	REPLACED RIVET & SPRING, INSTALLED	21047	\$31.32
OK	597	A2655981	06-01	M9	NEW STYLE EJECTOR, SAFETY & TEST	21047	\$69.98
WI	597	A2653326	06-01	DOESN'T ALWAYS CHAMBER	REPLACED TRIGGER HOUSING ASSY,	20616	\$19.01
OR	597	A2653339	06-01	ROUNDS.	INSTALLED NEW EJECTOR, SAFETY & TEST	20023	\$48.80
AL	597	A2659894	07-01	MISFIRES.	TEST FIRED WITH NO PROBLEMS, SENT TO	21056	\$22.50
NY	597	A2657736	07-01	M9	MANN & SON SPTG. GDS.	21177	\$20.00
AK	597	A2658877	07-01	M110	UPDATED EJECTOR, REPLACED ACTION	21147	\$10.00
NY	597	A2657869	07-01	DOES NOT FIRE ALL THE TIME.	SPRING, TESTED AND CLEANED.	21177	\$20.00
AL	597	A2657869	07-01	M201	CLEANED AND TEST FIRED.	21056	\$22.00
AL	597	A2657499	07-01	M10	CLEANED BOLT FACE, SAFETY & FUNCTION	21056	\$22.50
OK	597	A2658684	07-01	M9, M15, M23	CHECKED AND TESTED.	21047	\$43.37
OK	597	A2659808	07-01	M23	INSTALLED NEW STYLE EJECTOR & METAL	21047	\$29.58
OK	597	A2658365	07-01	M9	MAGAZINE, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2659884	07-01	M9	INSTALLED NEW STYLE EJECTOR.	21047	\$34.58
OK	597	A2659332	07-01	M9	ADJUSTED MAGAZINE ASSY, SAFETY & TEST	21047	\$29.58
OH	597	A2657923	07-01	MISFIRES.	INSTALLED NEW STYLE EJECTOR, SAFETY &	21047	\$29.58
OH	597	A2659582	07-01	REPAIR.	TEST FIRED.	21060	\$43.98
NY	597	A2659115	07-01	M138	INSTALLED NEW TYPE EJECTOR, CLEANED,	21060	\$92.57
					CHECKED AND TEST FIRED.	21177	\$20.00
					INSTALLED NEW TYPE EJECTOR, REPLACED		
					BOLT HANDLE & BOLT ASSY, CLEANED,		
					REPLACED EJECTOR, SAFETY & FUNCTION		
					CHECKED AND TESTED.		

OK	597	A2659496	07-01	M9	REPLACED EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2659604	07-01	M9, M10	REPLACED EXTRACTOR, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$31.55
AL	597	A2657920	07-01	M10, M23	REPLACED MAGAZINE CLIP, HONED CHAMBER.	21056	\$22.50
IL	597	A2654237	07-01		REPLACED RECEIVER AND TEST FIRED.	21028	\$54.09
NY	597	A2657523	07-01	M142	REPLACED TRIGGER HOUSING ASSY, SAFETY & FUNCTION CHECKED AND TEST	21177	\$20.00
MS	597	A2658167	07-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00
MI	597	A2662264	08-01	GUN WILL ONLY GROUP FROM 1 1/2" TO 2" AT 25 YDS.	CLEANED, RECROWNED, TESTED, RETURNED TO FACTORY.	21030	\$38.80
GA	597	A2661213	08-01	JAMS, TWISTS SHELLS.	COULD NOT VERIFY COMPLAINT, TEST FIRED WITH NO PROBLEMS	20300	\$45.00
KY	597	A2660395	08-01	M23	CUSTOMER STATES STILL JAMS AFTER I INSTALLED NEW EJECTOR & MAG. TEST	21072	\$18.00
NY	597	A2661404	08-01		FIT NEW EJECTOR, FUNCTION TESTED.	20312	\$32.79
OH	597	A2662706	08-01	ACTION STICKS, HOLE IN CAST ABOVE WHERE CLIP GOES ON GUN.	GROUND EJECTOR & GROVE IN BOLT CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75
OH	597	A2662782	08-01	JAMS.	GROUND EJECTOR SIDE, CLEANED CHECKED AND TEST FIRED.	21060	\$42.25
OH	597	A2662779	08-01	REPAIR.	GROUND SIDE OF EJECTOR FOR BOLT CLEARANCE, ADJUSTED RECOIL SPRING	21060	\$45.75
OH	597	A2662781	08-01	REPAIR.	GROUND SIT OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75
OK	597	A2661003	08-01	M9	INSTALLED NEW STYLE EJECTOR, ADJUSTED MAGAZINE, SAFETY & TEST	21047	\$29.58
KY	597	A2660395	08-01	M9, M23	INSTALLED NEW STYLE EJECTOR, REPLACED MAGAZINE AND TEST FIRED.	21072	\$22.23
NY	597	A2661115	08-01	M110	LOOSENE TRIGGER LINKAGE RIVET, ADJUSTED ACTION TIGHTNESS, REPLACED	21177	\$20.00
CT	597	A2663080	08-01	M9, M10, M23	POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$40.75
NY	597	A2662061	08-01	M145	REPLACED BOLT SPRING & BOLT SPRING RIVET, SAFETY & FUNCTION CHECKED AND	21177	\$20.00

OH	597	A2661436	08-01	CLIP MISSING.	REPLACED CLIP, BOLT ASSY & EJECTOR.	21060	\$98.30
CA	597	A2662395	08-01	M9, M23	REPLACED EJECTOR AND MAG AND TEST FIRED.	20106	\$38.85
CT	597	A2661142	08-01	M23	REPLACED EJECTOR, POLISHED CHAMBER, CHECKED OVER, CLEANED & OILED, SAFETY	20629	\$42.98
NY	597	A2660302	08-01	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
NY	597	A2661298	08-01	M137	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	A2662020	08-01	M25	REPLACED MOD. EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$42.98
MS	597	2963682M	08-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
MS	597	2963428M	08-01	WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
NY	597	A2665590	09-01	M137	ADJUSTED ACTION TIGHTNESS, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	A2665235	09-01	M9	ADJUSTED EJECTOR & MAGAZINE, SAFETY & TEST FIRED.	21047	\$32.23
NE	597	A2664419	09-01	MAG FALLS OUT.	ADJUSTED MAG LATCH, SHARPENED MAG SLOT AND TEST FIRED.	21106	\$27.40
OR	597	2963625M	09-01	M5	ADJUSTED OPERATING HANDLE RETAINING SPRING.	20200	\$10.00
NY	597	A2664560	09-01	M34	CLEANED SAFETY, FUNCTION CHECKED AND TESTED.	21177	\$20.00
OH	597	A2666373	09-01	SHELL JAMS IN BBL WHEN SHOT.	GROUND EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$47.75
AL	597	A2664655	09-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2663876	09-01	M23	HONED CHAMBER.	21056	\$22.50
OK	597	A2665075	09-01	M9, M23	INSTALLED NEW STYLE EJECTOR, REPLACED TRIGGER HOUSING, SAFETY & POLISHED CHAMBER, REPLACED MAGAZINE CLIP.	21047	\$71.19
AL	597	A2663004	09-01	M23		21056	\$31.28
AL	597	A2665663	09-01	M10	POLISHED CHAMBER.	21056	\$22.50

OK	597	A2666220	09-01	M23	REPLACED ACTION SPRING & RECEIVER PLUG, SAFETY & TEST FIRED.	21047	\$29.46
AL	597	A2665953	09-01	M23	REPLACED MAGAZINE CLIP.	21056	\$31.25
OR	597	A2664634	09-01		SHOOTS TO RIGHT, SIGHTS ARE OFF.		
NY	597	A2664038	09-01	M993	RESET SIGHTS, BORESIGHTED. SAFETY & FUNCTION CHECKED AND TESTED. NO FAULT FOUND.	20023	\$26.50
AL	597	A2666791	10-01	M5, M9	ADJUSTED BOLT HANDLE SPRING & EJECTOR.	21177	\$20.00
CT	597	A2667214	10-01	M25	CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	21056	\$22.50
OH	597	A2663510	10-01		GROUND EJECTOR FOR BOLT CLEARANCE, OPERATING HANDLE PULLS OFF GUN, SITTING IN BOX.	20629	\$40.75
OH	597	A2668880	10-01		REPLACED BOLT ASSY & BOLT HANDLE, GROUND SIDE OF EJECTOR TO CLEAR BOLT, CLEANED, CHECKED AND TEST FIRED.	21060	\$94.84
OH	597	A2668797	10-01		REPAIR. NOT FIRING, GUN JAMS AFTER BEING LOADED. GROUND SIDE OF NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.25
AL	597	A2667691	10-01	M10		21060	\$41.75
AL	597	A2666708	10-01	M10	HONED CHAMBER, CHECKED SAFETY	21056	\$22.50
AL	597	A2666917	10-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2667274	10-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2667145	10-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2666867	10-01		HONED CHAMBER. OPERATING HANDLE IS OK, ADJUSTED MAGAZINE, SAFETY & TEST FIRED.	21056	\$22.50
AL	597	A2666989	10-01	M10		21047	\$27.35
OH	597	A2668510	10-01		POLISHED CHAMBER. OPERATING HANDLE COMES OFF, SECOND TIME IN FOR SAME REPAIR.	21056	\$22.50
OH	597	A2667463	10-01		RECEIVER COCKED OPEN AND WILL NOT RELEASE. CLEANED, CHECKED AND TEST FIRED.	21060	\$84.84
OH	597	A2663186	10-01		BOLT PULL HAS FALLEN OFF, WON'T STAY ON. REPLACED BOLT ASSY & BOLT HANDLE, GROUND NEW STYLE EJECTOR, CLEANED, REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$83.84
						21060	\$85.36

OK	597	A2667408	10-01	M23	REPLACED BOLT SPRING & RIVET, SAFETY & TEST FIRED.	21047	\$30.42
OH	597	A2667227	10-01	PARTS MISSING.	REPLACED STOCK, CLEANED, CHECKED AND TEST FIRED.	21060	\$92.74
TX	597	A2668439	10-01	DOES NOT FEED PROPERLY.	TEST FIRED, SUSPECT AMMO PROBLEM.	21017	\$21.50
OK	597	A2670808	11-01	M9, M10	REPLACED BOLT RIVET & SPRING, INSTALLED NEW STYLE EJECTOR, SAFETY &	21047	\$33.77
MS	597	99999		WHSE INSPECTION.	WHSE INSPECTION.	107773	\$15.00
LA	597	294372M	-	M10	INSTALLED LONGER EXTRACTOR.	21025	\$24.09
OK	597	A2520507	-		INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$34.46
MN	597	AZ641643	-	M9, M23	POLISHED CHAMBER, ADJUSTED EJECTOR, SMOOTHED BOTTOM OF BOLT AND TEST REASSEMBLED MAG LATCH. REPLACED	20017	\$47.90
NY	597	7774992	-	M142	EJECTOR, SAFETY & FUNCTION CHECKED	21177	\$20.00
NY	597	27772868	-	M145	REPLACED BOLT SPRING & RIVET, BOLT HANDLE AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NY	597	296257M	-	M145	REPLACED BOLT SPRING & RIVET, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
OK	597	0946424M	-		REPLACED BOLT SPRING RIVET & BOLT HANDLE SPRING, SAFETY & TEST FIRED.	21047	\$33.97
CAN	597	999999.	-	CROSS THREADED.	REPLACED CLAMP SCREW.	268418	\$0.79
MI	597	2747049	-	M23	REPLACED EJECTOR AND TEST FIRED.	20108	\$21.15
IL	597	A2683030	2002		REPLACED EJECTOR, MAGAZINE BOX, REMOVED BURRS AT CHAMBER AREA AND	21028	\$40.73
CAN	597	999999	-	M9	REPLACED EJECTOR.	268418	\$6.38
IL	597	2950450	-	M10, M33	REPLACED EXTRACTOR AND MAGAZINE BOX, NEW BOLT HANDLE AND TEST FIRED.	21028	\$48.26
CAN	597	999999	-	M23	REPLACED MAG.	268418	\$17.11
MI	597	29427817	-	WON'T FEED LAST CARTRIDGE.	REPLACED MAGAZINE AND TESTED.	21054	\$25.69

CAN	597	999999	M23	REPLACED MAGAZINES.	268418	\$14.37
MS	597	A2653145	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00
MS	597	2962499M	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00
MS	597	2725756	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00

DAYS	INVOICE	
SHIP	#	DATE
1	149680	11-Mar-02
2	153553	13-Mar-02
1	148679	02-Apr-02
9	137104	19-Feb-02
1	137109	19-Feb-02
1	149379	14-Mar-02
1	137133	19-Feb-02
1	142611	14-Mar-02
1	149570	18-Feb-02
15	142163	13-Feb-02
5	83882	11-Feb-02
1	149678	11-Mar-02
2	150338	18-Mar-02
8	150325	11-Feb-02
34	111598	21-Feb-02
1	84171	15-Jan-02
1	137081	09-Mar-02
3	SH4886	18-Mar-02

CONFIDENTIAL

12 151209	01-Apr-02
2 SH4904	02-Apr-02
1 138729	13-Mar-02
1 149672	11-Mar-02
9 0	20-Feb-02
62 153123	07-Mar-02
3 132141	13-Feb-02
34 110396	17-Jan-02
58 83749	07-Feb-02
2 149577	11-Mar-02
12 151503	16-Feb-02
70 124483	13-Mar-02
6 149407	07-Feb-02
13 83875	11-Feb-02
23 153626	07-Mar-02
1 149679	11-Mar-02
96 123749	20-Feb-02
24 123294	14-Feb-02
2 142640	14-Mar-02

6 121414	10-Apr-02
25 123278	14-Feb-02
7 151583	16-Feb-02
1 136053	16-Feb-02
5 156192	02-Apr-02
1 68765	15-Jan-02
41 123264	26-Feb-02
10 91930	05-Mar-02
3 153551	21-Feb-02
77 111595	09-Feb-02
13 139228	09-Mar-02
25 110559	23-Mar-02
1 SH4917	02-Apr-02
1 149575	11-Mar-02
1 148518	02-Apr-02
3 SH4897	02-Apr-02
1 142613	14-Mar-02
30 112956	21-Feb-02
1 DK1475	08-Apr-02

1	143532	14-Feb-02
1	25294	14-Feb-02
1	137018	19-Feb-02
1	156036	05-Mar-02
5	151087	23-Feb-02
15	151655	23-Feb-02
1	25282	14-Feb-02
11	143735	07-Mar-02
4	137001	19-Feb-02
1	137078	19-Feb-02
1	137131	19-Feb-02
5	124490	13-Mar-02
6	141630	07-Feb-02
1	30957	15-Jan-02
24	25290	14-Feb-02
39	139865	25-Feb-02
0	131721	17-Jan-02
3	137127	19-Feb-02
232	84035	21-Feb-02

3	143775	07-Mar-02
70	140103	18-Mar-02
4	110527	18-Mar-02
108	134638	26-Feb-02
1	137879	17-Jan-02
3	149589	18-Feb-02
12	156225	13-Feb-02
1	137112	19-Feb-02
51	141310	10-Apr-02
59	122445	15-Apr-02
1	149509	16-Feb-02
1	136052	16-Feb-02
290	681	01-Apr-02
3	31484	11-Feb-02
1	68766	15-Jan-02
1	155959	05-Mar-02
5	132443	27-Feb-02
1	123013	13-Mar-02
23	115908	23-Feb-02

33	132570	29-Jan-02
1	142633	14-Mar-02
5	132466	07-Mar-02
23	137437	04-Mar-02
5	151793	16-Feb-02
1	150010	09-Feb-02
1	137022	19-Feb-02
3	137028	19-Feb-02
13	122421	15-Apr-02
23	156253	26-Feb-02
10	77153	07-Feb-02
21	156421	05-Mar-02
1	137049	19-Feb-02
4	122414	15-Apr-02
1	156323	13-Feb-02
1	69693	03-Apr-02
1	25283	14-Feb-02
1	31487	04-Mar-02
11	151150	01-Apr-02

4 132408	28-Feb-02
41 148203	19-Feb-02
11 151121	01-Apr-02
1 137097	09-Mar-02
17 134646	26-Feb-02
3 141514	18-Mar-02
6 138600	13-Mar-02
10 81039	02-Apr-02
1 132111	13-Feb-02
2 SH4751	22-Feb-02
1 149682	11-Mar-02
9 143690	23-Feb-02
5 69932	02-Apr-02
3 156464	09-Apr-02
30 104244	11-Feb-02
107 132132	13-Feb-02
1 137096	09-Mar-02
8 151584	16-Feb-02
24 110455	17-Jan-02

2	132421	27-Feb-02
24	134534	21-Feb-02
1	156137	12-Mar-02
55	148202	19-Feb-02
1	156373	13-Feb-02
1	153082	07-Mar-02
1	135088	19-Feb-02
23	141186	15-Feb-02
3	SH4706	29-Jan-02
1	25297	14-Feb-02
1	25280	14-Feb-02
12	122473	15-Apr-02
27	122461	15-Apr-02
4	122467	15-Apr-02
5	156143	12-Mar-02
20	155943	12-Mar-02
6	141658	07-Feb-02
4	SH4866	18-Mar-02
4	SH4865	18-Mar-02

1	149673	11-Mar-02
1	SH4875	18-Mar-02
3	156190	02-Apr-02
3	149578	11-Mar-02
2	137105	19-Feb-02
38	137429	04-Mar-02
13	138569	07-Feb-02
1	104241	11-Feb-02
3	SH4703	29-Jan-02
1	156007	05-Mar-02
1	156055	05-Mar-02
4	SH4779	22-Feb-02
21	151661	23-Feb-02
8	151644	23-Feb-02
18	155880	05-Mar-02
13	151175	01-Apr-02
2	132477	09-Mar-02
5	132574	29-Jan-02
19	70575	02-Apr-02

27 131707	17-Jan-02
22 151651	25-Feb-02
82 84037	21-Feb-02
2 30956	15-Jan-02
1 25285	14-Feb-02
1 149579	11-Mar-02
6 151103	25-Feb-02
19 70576	02-Apr-02
3 123757	20-Feb-02
19 83759	07-Feb-02
6 141785	23-Feb-02
3 143756	07-Mar-02
1 143533	14-Feb-02
1 149568	18-Feb-02
89 128439	07-Mar-02
13 151189	01-Apr-02
14 155916	05-Mar-02
13 151524	16-Feb-02
1 155877	26-Feb-02

5 151796	16-Feb-02
20 SH4786	04-Mar-02
1 149681	11-Mar-02
2 132461	27-Feb-02
4 138738	12-Mar-02
21 1256	18-Mar-02
290 84034	21-Feb-02
1 149370	16-Feb-02
1 149677	11-Mar-02
1 142628	14-Mar-02
4 676	01-Apr-02
5 750	01-Apr-02
45 140106	18-Mar-02
4 142627	14-Mar-02
1 123759	20-Feb-02
1 123748	20-Feb-02
3 134976	15-Feb-02
1 125219	09-Feb-02
91 122472	15-Apr-02

4	149115	18-Feb-02
13	155936	05-Mar-02
1	156154	12-Mar-02
2	156099	12-Mar-02
19	110480	17-Jan-02
4	132473	09-Mar-02
6	156405	26-Feb-02
15	110460	17-Jan-02
1	137562	09-Feb-02
3	128852	29-Jan-02
3	143754	07-Mar-02
3	149676	11-Mar-02
6	151105	25-Feb-02
6	141655	07-Feb-02
8	128444	09-Mar-02
1	138698	12-Mar-02
1	110517	23-Mar-02
28	111632	07-Mar-02
1	DK1503	08-Apr-02

2	141684	07-Feb-02
12	110557	23-Mar-02
18	137595	09-Feb-02
1	137577	09-Feb-02
1	138676	12-Mar-02
7	138688	13-Mar-02
1	135092	19-Feb-02
13	143536	14-Feb-02
5	143741	07-Mar-02
1	138728	13-Mar-02
14	137123	19-Feb-02
1	68709	15-Jan-02
6	151106	25-Feb-02
8	155989	11-Mar-02
1	137088	09-Mar-02
2	150054	03-Apr-02
1	137090	09-Mar-02
9	150060	03-Apr-02
1	123767	20-Feb-02

1	156127	12-Mar-02
1	156104	12-Mar-02
1	123773	20-Feb-02
25	138791	16-Apr-02
1	115903	23-Feb-02
5	143515	11-Feb-02
2	143501	11-Feb-02
13	110504	23-Mar-02
9	128440	07-Mar-02
30	133332	13-Mar-02
1	123745	20-Feb-02
7	138673	12-Mar-02
1	123752	20-Feb-02
6	132449	27-Feb-02
4	132458	27-Feb-02
5	110520	23-Mar-02
1	DK1307	03-Apr-02
8	141643	07-Feb-02
7	138707	12-Mar-02

3 135846	27-Feb-02
17 137019	19-Feb-02
15 131717	17-Jan-02
38 110399	17-Jan-02
1 137582	09-Feb-02
6 138640	12-Mar-02
1 138700	13-Mar-02
5 150004	09-Feb-02
1 132423	27-Feb-02
5 132596	11-Feb-02
7 143737	07-Mar-02
3 132478	09-Mar-02
7 152851	09-Apr-02
3 142874	09-Apr-02
1 104248	05-Mar-02
11 151572	16-Feb-02
17 151898	21-Feb-02
4 156451	07-Mar-02
1 76561	09-Apr-02

7	143755	07-Mar-02
44	141694	07-Feb-02
5	132575	29-Jan-02
1	149369	16-Feb-02
3	11339	29-Jan-02
2	156042	11-Mar-02
12	155944	05-Mar-02
2	156195	02-Apr-02
6	132497	09-Mar-02
7	137025	19-Feb-02
19	138594	13-Mar-02
6	156081	11-Mar-02
1	149576	11-Mar-02
1	104239	11-Feb-02
16	110551	23-Mar-02
9	131646	25-Feb-02
9	138762	15-Apr-02
2	126856	14-Feb-02
1	143724	14-Feb-02

6 121044	11-Feb-02
19 155856	05-Mar-02
1 128420	28-Feb-02
2 138551	07-Feb-02
2 141681	07-Feb-02
7 138631	12-Mar-02
13 110507	23-Mar-02
1 123747	20-Feb-02
4 149117	18-Feb-02
5 156091	12-Mar-02
1 124494	13-Mar-02
1 123754	20-Feb-02
1 123774	20-Feb-02
1 137553	09-Feb-02
1 137556	09-Feb-02
1 137561	09-Feb-02
1 137533	08-Feb-02
4 SH4788	22-Feb-02
1 SH4868	18-Mar-02

2	141670	07-Feb-02
10	138755	15-Apr-02
52	110405	17-Jan-02
7	150018	09-Feb-02
7	150017	09-Feb-02
7	150016	09-Feb-02
1	150019	09-Feb-02
13	141760	18-Mar-02
6	SH4759	22-Feb-02
5	132571	29-Jan-02
5	132442	27-Feb-02
7	SH4832	04-Mar-02
6	138702	13-Mar-02
7	138595	13-Mar-02
14	138607	13-Mar-02
7	149116	18-Feb-02
13	124057	03-Apr-02
1	156337	13-Feb-02
1	141685	07-Feb-02

1 123771	20-Feb-02
1 123766	20-Feb-02
1 123769	20-Feb-02
1 123772	20-Feb-02
1 123770	20-Feb-02
11 151081	25-Feb-02
12 123744	20-Feb-02
16 110499	23-Mar-02
1 138571	07-Feb-02
1 149674	11-Mar-02
4 123279	14-Feb-02
1 123768	20-Feb-02
7 116873	02-Apr-02
10 151100	23-Feb-02
11 151118	01-Apr-02
10 142846	02-Apr-02
20 139230	09-Mar-02
5 1186	18-Mar-02
12 123330	26-Feb-02

6 137125	19-Feb-02
21 156423	05-Mar-02
4 156376	26-Feb-02
12 155942	05-Mar-02
1 148670	02-Apr-02
0 151507	16-Feb-02
25 123018	13-Mar-02
1 123751	20-Feb-02
2 156040	05-Mar-02
8 155990	05-Mar-02
1 SH4850	04-Mar-02
1 142848	01-Apr-02
2 SH4796	22-Feb-02
6 156012	05-Mar-02
1 137079	09-Mar-02
2 156097	12-Mar-02
6 156413	26-Feb-02
3 132475	09-Mar-02
1 148664	02-Apr-02

2 156197	02-Apr-02
21 57412	25-Feb-02
4 138637	12-Mar-02
1 SH4752	22-Feb-02
27 122327	07-Mar-02
5 132485	07-Mar-02
7 110492	15-Jan-02
25 110451	17-Jan-02
3 151797	16-Feb-02
1 149572	18-Feb-02
1 104249	05-Mar-02
1 156327	13-Feb-02
1 80451	27-Feb-02
5 156188	02-Apr-02
7 139860	25-Feb-02
1 149573	18-Feb-02
3 149574	18-Feb-02
5 138809	16-Apr-02
3 143748	07-Mar-02

4	SH4776	22-Feb-02
13	138686	12-Mar-02
5	138606	16-Apr-02
9	143686	23-Feb-02
4	143523	11-Feb-02
8	143760	07-Mar-02
8	132468	07-Mar-02
4	142835	18-Mar-02
3	143816	09-Apr-02
6	SH4890	02-Apr-02
1	SH4820	04-Mar-02
5	138718	12-Mar-02
1	149675	11-Mar-02
16	SH4853	18-Mar-02
4	156406	26-Feb-02
5	148510	02-Apr-02
7	156156	02-Apr-02
13	151527	16-Feb-02
1	150328	25-Feb-02

16 SH4856	18-Mar-02
4 SH4877	18-Mar-02
6 122496	15-Apr-02
17 110547	23-Mar-02
26 SH4845	02-Apr-02
1 151051	25-Feb-02
12 151081	25-Feb-02
24 110562	23-Mar-02
1 137580	09-Feb-02
6 138670	13-Mar-02
4 132459	27-Feb-02
12 143511	11-Feb-02
9 143729	14-Feb-02
1 128433	07-Mar-02
3 128873	09-Apr-02
2 SH4895	02-Apr-02
6 SH4835	04-Mar-02
6 142831	18-Mar-02
2 149128	18-Feb-02

1	137139	09-Mar-02
5	132486	09-Mar-02
9	143656	27-Feb-02
16	153607	07-Mar-02
19	110476	17-Jan-02
10	138757	15-Apr-02
1	156150	12-Mar-02
1	133516	09-Apr-02
6	156070	11-Mar-02
2	141676	07-Feb-02
1	138711	12-Mar-02
8	143774	07-Mar-02
9	143653	27-Feb-02
2	143818	09-Apr-02
7	142857	09-Apr-02
1	142863	09-Apr-02
1	SH4851	04-Mar-02
4	SH4843	04-Mar-02
14	155914	05-Mar-02

8 143527	11-Feb-02
4 142828	18-Mar-02
6 138714	12-Mar-02
2 137024	19-Feb-02
7 156387	26-Feb-02
1 DK1429	08-Apr-02
1 104242	11-Feb-02
8 111599	21-Feb-02
1 150070	03-Apr-02
7 131641	25-Feb-02
1 SH4854	04-Mar-02
1 SH4867	18-Mar-02
5 SH4892	02-Apr-02
4 SH4878	18-Mar-02
7 143663	23-Feb-02
1 150068	03-Apr-02
19 155854	05-Mar-02
14 151213	01-Apr-02
4 155883	05-Mar-02

13	121404	18-Mar-02
1	149368	16-Feb-02
8	151137	01-Apr-02
3	155986	05-Mar-02
7	156003	11-Mar-02
12	151211	01-Apr-02
1	DK1306	03-Apr-02
1	DK1305	03-Apr-02
3	155890	05-Mar-02
4	132460	27-Feb-02
5	139221	14-Jan-02
1	133331	13-Mar-02
4	118685	02-Apr-02
1	SH4817	22-Feb-02
6	138713	12-Mar-02
10	138752	15-Apr-02
5	132434	27-Feb-02
1	138626	12-Mar-02
2	138612	13-Mar-02

1	132441	27-Feb-02
6	138591	13-Mar-02
15	110531	23-Mar-02
1	155974	05-Mar-02
9	138754	15-Apr-02
8	151136	01-Apr-02
4	SH4775	22-Feb-02
5	SH4893	02-Apr-02
4	SH4860	18-Mar-02
6	138704	12-Mar-02
4	138639	12-Mar-02
7	138677	12-Mar-02
6	138710	13-Mar-02
13	138773	15-Apr-02
12	143692	23-Feb-02
19	138736	15-Apr-02
7	SH4830	04-Mar-02
1	SH4765	22-Feb-02
4	SH4861	18-Mar-02

9 142832	18-Mar-02
26 SH4847	02-Apr-02
7 88632	02-Apr-02
7 142830	18-Mar-02
1 DK1383	04-Apr-02
15 138981	09-Mar-02
10 143727	14-Feb-02
6 149571	18-Feb-02
14 155919	05-Mar-02
24 156263	26-Feb-02
1 156114	12-Mar-02
1 132599	11-Feb-02
1 123750	20-Feb-02
24 142150	13-Feb-02
1 137095	09-Mar-02
1 123753	20-Feb-02
10 137135	09-Mar-02
1 123764	20-Feb-02
13 116850	15-Feb-02

0 123763	20-Feb-02
1 D1463	08-Apr-02
1 DK1481	08-Apr-02
1 DK1418	08-Apr-02