

Remington Arms
MayfieldQuality Manual 6-2
Appendix A
Form C-1036

First Article Inspection - Mayfield Results

Part Number
Part NameF 300441
SCOPE RAILDrawing #
Rev. Level

D-300441

Vendor
Date Received
Lot #Minalex
9-11-00
1,113

SAMPLES							Average	Min	Max
#	Feature Name	#1	#2	#3	#4	#5			
1	5.000 $\pm$.005	5.00	5.00	5.00	5.00	5.00	#DIV/0!	0.0000	0.0000
2	4.422 $\pm$.005	4.422	4.424	4.421	4.422	4.421	#DIV/0!	0.0000	0.0000
3	3.672 $\pm$.005	3.672	3.672	3.672	3.672	3.672	#DIV/0!	0.0000	0.0000
4	1.212 $\pm$.005	1.212	1.212	1.212	1.212	1.212	#DIV/0!	0.0000	0.0000
5	.462 $\pm$.005	.461	.462	.462	.461	.462	#DIV/0!	0.0000	0.0000
6	.175 $\pm$.005	.174	.174	.174	.174	.175	#DIV/0!	0.0000	0.0000
7	4.710 $\pm$.005	4.713	4.713	4.713	4.713	4.713	#DIV/0!	0.0000	0.0000
8	3.960 $\pm$.005	3.961	3.959	3.960	3.961	3.960	#DIV/0!	0.0000	0.0000
9	3.210 $\pm$.005	3.210	3.209	3.210	3.209	3.209	#DIV/0!	0.0000	0.0000
10	.750 $\pm$.005	.750	.750	.750	.750	.750	#DIV/0!	0.0000	0.0000
11	.234 $\pm$.003	.234	.234	.234	.234	.234	#DIV/0!	0.0000	0.0000
12	.413 $\pm$.005	.412	.413	.413	.413	.413	#DIV/0!	0.0000	0.0000
13	.147 $\pm$.003	.146	.146	.146	.146	.146	#DIV/0!	0.0000	0.0000
14	.147 $\pm$.003	.146	.146	.146	.146	.146	#DIV/0!	0.0000	0.0000
15	.826 $\pm$.005	.825	.826	.825	.826	.826	#DIV/0!	0.0000	0.0000
16	.731 $\pm$.005	.730	.730	.730	.731	.731	#DIV/0!	0.0000	0.0000
17	R .695 $\pm$.003	.693	.695	.695	.698	.693	#DIV/0!	0.0000	0.0000
18	R .935 $\pm$.003	.936	.930	.931	.932	.933	#DIV/0!	0.0000	0.0000
19	.413 $\pm$.005	.413	.413	.413	.412	.413	#DIV/0!	0.0000	0.0000
20	depth of slot	.090	.089	.090	.090	.090	#DIV/0!	0.0000	0.0000
21							#DIV/0!	0.0000	0.0000
22							#DIV/0!	0.0000	0.0000
23							#DIV/0!	0.0000	0.0000
24							#DIV/0!	0.0000	0.0000
25							#DIV/0!	0.0000	0.0000
26							#DIV/0!	0.0000	0.0000
27							#DIV/0!	0.0000	0.0000
28							#DIV/0!	0.0000	0.0000
29							#DIV/0!	0.0000	0.0000
30							#DIV/0!	0.0000	0.0000

Inspected
Approved By
Rejected By

JOHN & CALVIN

Date
Date

9/19/00

Revised By: M. Goelmboski
Revision Date: 2/14/00

First Article Inspection

ET06380