

PROCESS RECORD CHANGE AUTHORIZATION

FEBRUARY 2, 1973

**"...POSSIBLE CONNECTOR-SEAR
INTERFERENCE. AT LEAST
TWENTY IN 1972, AND FOUR SO
FAR IN 1973 CUSTOMER
COMPLAINTS INCLUDING ONE
PERSONAL INJURY ARE
ATTRIBUTED TO THIS
INTERFERENCE."**



NTBOOK003