

Product deficiencies known or suspected in 1975 - Exhibit 15.

IREM 0018349

IREM 0027644

MINUTE #6 - 1975

-8-

March 21, 1975

BUSINESS MEETING - contd.RESEARCH PERFORMANCE - contd.ProgramRelease Design
Schedule

Model 788 Improvements -
Design will be released in the second
half of 1975.

April, 1975

Model 700 Improvements -
The three position safety is being
reviewed. Recommendations will be
made in the second half of 1975.

January, 1975

EXHIBIT 16PRODUCT DEFICIENCIES (KNOWN OR SUSPECTED) 1975Remington 3200 -Model 1100 -Model 1100 and 870Model 742 -Model 700 - three position safety would be desirable.

NTBOOK009