

NEW MECHANICAL TRAP - contd.OPERATIONS COMMITTEEILION DIVISION

APRIL 21, 1977

SPECIAL REPORTSMOHAWK 600 AND MODEL 700 FIRE CONTROL REVIEWMOHAWK 600 RIFLE

R & D reported that drawings have been transmitted to the plant to alter the Mohawk 600 Fire Control. The Fire Control Housing presently used on the M/700 has been modified so that it will fit the Mohawk 600. This change will yield a common Fire Control Housing for the Mohawk 600 and M/700 rifle. It will reduce cost, as the factory cost of the M/700 Fire Control Housing is less than the factory cost of the Mohawk 600 Fire Control Housing. This change should also improve the detent action of the Mohawk 600 Fire Control. The side plate on the M/700 Housing is heat treated. This is the surface the hardened steel detent ball is spring loaded against to obtain the two Safety positions.

MOHAWK 600 AND MODEL 700 RIFLES FOR EXPORT TO AUSTRALIA

R & D reported that one thousand Mohawk 600 rifles were shipped to Australia and stopped by the customs officials as being unacceptable for importation. This action was taken because the customs officials claimed the trigger adjusting screws should have a mechanical locking means.

It has been our experience with the Mohawk 600, M/721, M/722 and M/700 rifles that the trigger adjusting screws stay in adjustment. The screws on the Mohawk 600, M/722, 721 were staked and sealed

IREM 0028207 1

IREM 0027509 1



NTBOOK036