

PRODUCT SAFETY SUB-COMMITTEE
ILION DIVISION

DECEMBER 7, 1981

MINUTE #8 - 1981

POLICY FOR DEALING WITH BOLT
LOCKS ON MODEL 700 AND MODEL
40X (B.C.&R) FIREARMS RETURNED
FOR REPAIRS

THERE WAS DISCUSSION OF PROCEDURES TO BE FOLLOWED IN REPAIRING FIREARMS WITH BOLT LOCKS. SINCE THE ABSENCE OR PRESENCE OF A BOLT LOCK IS NOT A SAFETY PROBLEM, DETERMINATION OF THE POLICY TO FOLLOW IN THESE CIRCUMSTANCES WAS NOT A MATTER FOR THE PRODUCT SAFETY SUBCOMMITTEE.

