

Remington-Union

REMINGTON ARMS COMPANY, INC.

PATENT

SPEEDING BREAKERS
TRAPS
POUNDER METAL PARTS
ILLION, NEW YORK
BRIDGEPORT, CONNECTICUT
LONGVIEW, ARKANSAS

MANUFACTURERS OF
SPORTING FIREARMS, AMMUNITION
TRAPS
TARGETS
ILLION, NEW YORK 13357
TELEPHONE 351-3347

OFFERS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, ADA, OKLAHOMA
ATLANTA, GEORGIA
INDIAN, OHIO
CABLE—ARTERY, BRIDGEPORT

MAY 11, 1982

Illion, New York
May 13, 1982

TO: RECOMMENDED GUNSMITH INFORMATION BULLETIN

MODEL 700 - CHANGE IN OPERATION

CC1143

Market research, over the past several years, shows that customer interest in the bolt lock feature on the Model 700 rifle has declined. As a result, we have removed it.

Elimination of the bolt lock period the bolt handle to be raised when the safety switch is either in the "S" or "F" position, simplifying loading and unloading. Appropriate changes in the instruction books have been made.

Since this change does not involve any product obsolescence, the order number will remain the same and there will be no formal trade announcement. Any gun returned to Illion Arms Service for repair will be returned to the customer with the same style safety switch it had when received.


RJSTJ:tpj

R. J. St. John

PR



NTBOOK177



IREN 00198381