

REMINGTON MODEL 700 OWNERS MANUAL  
SUMMARY OF WARNINGS AND INSTRUCTIONS

<u>ADJUSTMENT</u>	<u>LUBRICATION</u>	<u>DIAGRAM/PARTS</u>	<u>BOLT LOCK LOAD/UNLOAD</u>	<u>CAUTION</u>
11/75 TP - turn screw no minimum OT - back off 1/8 turn after firing. Engagement - no adjustment recommended (p. 1)	Remove from stock & clean in solvent, wipe clean. No recommendation on lubricant. <u>p. 1</u> Clean with good grade petroleum solvent and re-oil very lightly. When shooting in freezing weather, remove excess oil. For best results, use dry graphite if necessary. (p. 6)	Exploded diagram <u>(p. 2)</u> Fire control system parts including trigger connector for sale <u>(p. 3)</u> Parts made to close dimensions, may require slight adjustment or fitting to assure proper functioning. (p. 5)	Bolt lock on safe, unload by cycling bolt. (p. 1)	
1/71 "	"	"	"	
4/71 "	"	"	"	
2/72 ?	?	"	"	
4/72 ?	?	"	"	
12/72 TP- adjustment less than 3 lbs. not recommended. OT-adjustment back out 1/16 turn. <u>(p. 2)</u> Remington disclaims responsibility for alterations not made at factory. (p. 8)	Checked periodically by competent gunsmith to ensure proper inspection. <u>(p. 7)</u>	"	"	

<u>ADJUSTMENT</u>	<u>LUBRICATION</u>	<u>DIAGRAM/PARTS</u>	<u>BOLT LOCK LOAD/UNLOAD</u>	<u>CAUTION</u>
4/73 ?	"	"	" ?	"
1/74 ?	"	"	" ?	"
4/74 ?	"	"	" ?	" ?
9/74 ?	"	"	" ?	" ?
11/74 ?	"	"	" ?	" ?
1/75 ?	"	"	" ?	" ?
2/75 ?	"	"	" ?	" ?
11/75 No adjustment by owner is recommended. Return to factory or approved Remington gunsmith. (p. 2)	" (pp. 1,2)	" (pp. 3,4)	Add step of reengaging safety. Also instructs to point in safe direction. Different instructions for unloading bolt, use floorplate. (p. 1) <hr/> Put rifle on safe before closing bolt on live round. (p. 2)	" Point in safe direction. (p. 1)
1/77 "	"	"	"	"
1/78 "	"	"	"	"
1/79 No parts prices. (pp. 3,4)	"	"	"	"
2/79 No parts prices and some restricted parts. (pp. 4,5)	"	"	"	"

NTBOOK269

ADJUSTMENT

LUBRICATION

DIAGRAM/PARTS

BOLT LOCK  
LOAD/UNLOAD

CAUTION

780 Do not make adjustments including trigger, sear, notch.  
(p. 3)  
Must be made at factory or Remington recommended gunsmith. Never remove trigger mechanism or adjust it.  
(p. 5)

Inspected periodically by Remington or recommended gunsmith.  
(p. 11)  
Clean with a gun cleaning solvent.  
(p. 13)  
Apply thin coat oil to prevent rust.  
(p. 13)

Centerfire rifle receivers not sold separately.  
(p. 14)  
Exploded view does not include fire control system.  
(p. 15)  
Trigger assembly sold as unit.  
(p. 16)

Never pull trigger while on safe. Even when safety is on, careless handling can cause rifle to fire.  
(p. 4)  
Includes intermediate step of reengaging safety. Special instruction if cartridge slides on chamber.  
(p. 8)

Check firearm periodically to make sure mech. correct  
(p. 2)  
Do not play with safety switch.  
(p. 2)  
Never put finger on trigger unless to fire.  
(p. 5)

6/80 "

"

"

"

"

7/82 "

Recommends du Pont Teflon wet lubricant.  
(p. 11)  
Identifies 4 points to spray lubricant and instructs to do twice, once to lube and second to clean then shake off.  
(p. 12)  
Clean frequently, before and after long storage, adverse conditions, moisture, exposed to dirty conditions.  
(p. 13)  
Excessive use of a non-recommended lubricant could cause serious function problems possibly leading to accidental firing.  
(p. 12)

Trigger assembly sale is restricted.  
(p. 18)

Do not touch trigger while moving safety switch.  
(p. 4)

After lubrication and cleaning check FBC 10 times. If it fails to cock return to factory or Remington recommended gunsmith.  
(p. 13.)



ADJUSTMENT

LUBRICATION

DIAGRAM/PARTS

BOLT LOCK  
LOAD/UNLOAD

CAUTION

Over lubrication avoided  
at all times, thin coat of  
Remington oil all needed.  
If stored, carefully  
cleaned and thoroughly  
oiled when reused, all  
excess lubricant must be  
removed. Recommends  
Remington oil.  
(p. 11)

783 "  
786 "  
784 "  
788 "

"  
"  
"  
"

"

"

"  
"  
"

Don't rely on the  
safety switch.  
(p. 3)

"

"  
"  
"

Learn how  
to handle  
firearms  
safely,  
failure to  
obey these  
rules can  
result  
serious  
personal  
injury.  
(p. 2)

