

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 22775
OUTSIDE WORK: No DATE: 10-15-70
FROM: MARKLEYSBURG,
FIRED AMMO TYPE: _____ PA.
& CONDITION: _____ GUN #: 6262918
PROOF: R.E.P. INSP.: 9 TEST: _____ CODE: 05-7/69
HEADING: O.K. GA./CAL.: 22-250
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: FOLLOWS DOWN WHEN SAFETY IS PUSHED OFF.

INCIDENT: _____

COMMENTS: THE DIMENSION FROM THE TOP OF THE TRIGGER TO
CENTER OF TRIGGER PIN HOLE BEING .011 OVERSIZE
ELIMINATES MOST OF THE CLEARANCE NEEDED FOR THE
TRIGGER-CONNECTOR TO RETRACT WITH THE SAFETY ON

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 22775
OUTSIDE WORK: NO DATE: 10-15-70
FROM: MARKLEYSBURG,
FIRED AMMO TYPE: _____ PA.
& CONDITION: _____ GUN #: 6262918
PROOF: R.E.P. INSP.: 9 TEST: _____ CODE: OS = 7/69
HEADING: O.K. GA. CAL.: 22-250
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: FOLLOWS DOWN WHEN SAFETY IS PUSHED OFF,

INCIDENT: _____

COMMENTS: THE DIMENSION FROM THE TOP OF THE TRIGGER TO
CENTER OF TRIGGER PIN HOLE BEING .011 OVERSIZE
ELIMINATES MOST OF THE CLEARANCE NEEDED FOR THE
TRIGGER-CONNECTOR TO RETRACT WITH THE SAFETY ON

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: NEW R #: 22730
 OUTSIDE WORK: No DATE: 10-16-70
 FROM: LIVONIA, MICH.
 FIRED AMMO TYPE: _____ GUN #: 6278113
 & CONDITION: _____
 PROOF: -R.E.P. INSP.: _____ TEST: _____ CODE: _____
 HEADING: _____ GA./CAL.: 3006
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: _____ APPROVED: _____
 TEST: FUNCTION ONLY APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON ^{1.080}1.083 DIMENSION (TRIGGER CLEARANCE).

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT, ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD WORK O.K.