

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 22730
OUTSIDE WORK: No DATE: 10-16-70
FRO: LIVONIA,
FIRED AMMO TYPE: _____ MICH.
& CONDITION: _____ GUN #: 6278113
PROOF: R.E.P. INSP.: _____ TEST: _____ CODE: _____
HEADING: _____ GA./CAL.: 3006
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON ^{1.080}1.083 DIMENSION (TRIGGER CLEARANCE).

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT,
ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR
STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD
WORK O.K.