

P.I. No GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 ADLGENERAL CONDITION: GoodR # : 07367OUTSIDE WORK: NoDATE: 4-26-71FROM: MONTGOMERY WARD

FIRED AMMO TYPE: _____

& CONDITION: _____

GUN # : 6204725PROOF: REP.

INSP: _____

TEST: 41CODE: XR = 12/68HEADING: O.K.GR./CAL.: 270 WIN.

BREACH OPENING: _____

CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No.

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS.COMPLAINT: "FIRED WHEN BOLT WAS CLOSED."

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3276

COMMENTS: COULD NOT DUPLICATE CUSTOMER'S MALFUNCTION.HOWEVER, TRIGGER-CONNECTOR CLEARANCE BEING EXCESSIVE & TOO HEAVY LUBRICANT MAY HAVE CONTRIBUTED TO SUCH A FAILURE IN COLD TEMPERATURES.5 INJECTOR .006 OVERSIZE (1.089)TRIGGER .009 UNDERSIZE (1.067)REPLACED TRIGGER & CONNECTOR ENGAGEMENT O.K.

1 of 1

P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 ADLGENERAL CONDITION: GoodR # : 07367OUTSIDE WORK: NODATE: 4-26-71FROM: MONTGOMERY WARD

FIRED AMMO TYPE: _____

CONDITION: _____

GUN # : 6204725PROOF: REP.INSPECTION: 9TEST: 41CODE: XR = 12/68HEADING: O.K.GR./CAL.: 270 WIN.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO.

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTSCOMPLAINT: "FIRED WHEN BOLT WAS CLOSED"INCIDENT: -PLAINTIFF'S
EXHIBIT3276COMMENTS: COULD NOT DUPLICATE CUSTOMER'S MALFUNCTION.HOWEVER, TRIGGER-CONNECTOR CLEARANCE BEING EXCESSIVE & TOO HEAVY LUBRICANT MAY HAVE CONTRIBUTED TO SUCH A FAILURE IN COLD TEMPERATURES.CONNECTOR .006 OVERSIZE (1.089)TRIGGER .009 UNDERSIZE (1.067)1 of 1REPLACED TRIGGER & CONNECTOR ENGAGEMENT O.K.