

Customer Complaint
CHIP

P.I. NO GUN EXAMINATION REPORT NUMBER MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 010030
OUTSIDE WORK: NO DATE: 5-1-72
FROM: ODELL HOWE, CO.
FIRED AMMO TYPE: — GREENPRESSED, N.C.
& CONDITION: ASSEMBLER'S GUN #: 6489469
PROOF: R.F.F.-H INSP.: 51 TEST: 13 CODE: EU 10/71
HEADING: O.K. EA./OAL.: 3006
BREACH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED:
CHAMBER: O.K. APPROVED:
TEST: NO. APPROVED:
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN COMPONENTS. CONNECTOR, SEAR ENGAGE-
MENT = .008 MIN. 13.020 ALSO FOUND METAL CHIP
BETWEEN TRIGGER & CONNECTOR.

COMPLAINT: WILL NOT FIRE.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE METAL CHIP BETWEEN THE TRIGGER AND
CONNECTOR REDUCED THE CONNECTOR-SEAR ENGAGE-
MENT TO ZERO CAUSING THE FOLLOWS DOWN.