

700 Cust. Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700GENERAL CONDITION: NEWR #: 025800OUTSIDE WORK: NODATE: 12-14-72FROM: BILL'S SPT. # HOBBY ^{SHOP}

FIRED AMMO TYPE: _____

ONEONTA, N.Y.

& CONDITION: _____

GUN #: 6365666PROOF: R.E.P.-C INSP.:BBTEST: 29CODE: WT= 8/70HEADING: O.K.GR./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. 15.020)CONNECTOR CLEARANCE ON TRIGGER = 1.073 (MODEL DRAWING = 1.079) ^{1.076}BURRS ON TOP SIDES OF TRIGGER.COMPLAINT: GUN FIRED WHEN SAFETY WAS PUSHED OFF.INCIDENT: FOLLOW DOWN.COMMENTS: THE TRIGGER BIND COULD CAUSE FAILURE TORETRACT AND FOLLOW DOWN, THE UNDER MIN. ENGAGEMENT CONTRIBUTING TO THE MALFUNCTION.

EXHIBIT

19PLAINTIFF'S
EXHIBIT3196

AL 0029726