

*Cust Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDLGENERAL CONDITION: GOOD R #: 027088OUTSIDE WORK: NO DATE: 12-18-72FIRED AMMO TYPE: - FROM: VALLEY HOME SUPPLY CO.& CONDITION: ASSEMBLER - P MILESBURG, PA.PROOF: R.E.P.-D INSP.: 9 TEST: 13 GUN #: 6261266HEADING: O.K. CODE: OS = 7/69BREECH OPENING: - GA./CAL.: 308 WIN.RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: \_\_\_\_\_TEST: NO APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

EVIDENCE OF TRIGGER BURRS BINDING. TRIGGER 1.074  
(MODEL DRAWING 1.076) EXCESSIVE LUBRICANT-TOO HEAVY.  
TRIGGER CONNECTOR-SEAR ENGAGEMENT .015 (MIN. 15.020)

COMPLAINT: "FIRED WHEN SAFETY WAS RELEASED"INCIDENT: FOLLOW-DOWN.

COMMENTS: THE TRIGGER BIND, HEAVY LUBRICANT COMBINATION  
PROBABLY CAUSED THE FOLLOW DOWN.

PLAINTIFF'S  
EXHIBIT

3190

AL 0029720