

*Cust. Compl.*P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: NEWR #: 027329OUTSIDE WORK: NODATE: 1-2-73FROM: OSHMAN'S
SPORTING GOODS CO.FIRED AMMO TYPE: -BEAUMONT, TEXAS.& CONDITION: ASSEMBLER 56GUN #: 6521466PROOF: R.E.P.-M INSP.: 73 TEST: 13CODE: AW = 3/72HEADING: O.K.GR./CAL.: 3006BREECH OPENING: -CHECKED BY: CIPROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

COMPLAINT: GUN FIRED WHEN SAFETY WAS REMOVEDINCIDENT: FOLLOW DOWNCOMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. THE PRESENCE OF EXCESSIVE LUBRICANT
POSSIBLY CONTRIBUTED TO POOR TRIGGER RETRACT-
ION AND CAUSED FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3187

AL 0029717