

Cast Conyfl.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 000394

OUTSIDE WORK: NO DATE: 1-9-73

FROM: JOHN'S SPORTS CENTER

FIRE AMMO TYPE: - PITTSBURGH, KAN.

& CONDITION: ASSEMBLER 97 GUN #: 6432940

PROOF: R.E.P.-L INSE.: 73 TEST: 84 CODE: CU-4/71

HEADING: - GR./CAL.: 243 WIN.

BREACH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: 0.1K. APPROVED: _____

CHAMBER: 0.1K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BOLT CAM MARRED BY SAFETY. GROOVE CUT INTO
LEFT REAR OF HOUSING BY FIRING PIN HEAD. SEAR-
TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. IS .020)
CONNECTOR BINDING ON TRIGGER.

COMPLAINT: "WENT OFF WHEN THE BOLT WAS CLOSED"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3184

COMMENTS: THE TRIGGER CONNECTOR PROBABLY FAILED TO
RETRACT INTO POSITION UNDER THE SEAR, ALLOWING
THE FIRING PIN TO FOLLOW DOWN.