

ND-6942-1 Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: GOOD

OUTSIDE WORK: SCOPE MOUNTED

FIRED AMMO TYPE: —

& CONDITION: —

PROOF: R.E.P.

INSPECTION: U

TEST: ?

HEADING: O.K.

BREECH OPENING: —

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: —

COMPONENT CONDITION: (Damaged, Broken, Old Style)

BOLT HANDLE BROKEN OFF. TRIGGER BINDING -
HEAVY LUBRICANT - CONNECTOR STUCK TO
TRIGGER. CORNER OF SEAR BROKEN DOWN.

COMPLAINT: FIRES WHEN SAFETY IS TAKEN OFF.

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3181

COMMENTS: THE TRIGGER BINDING AS A RESULT OF THE
DRIED OUT LUBRICANT FAILED TO RETRACT,
REMAINING IN FIRED POSITION, CAUSED THE
FOLLOW DOWN.

AL (X)29711