

Custom Gun

P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 001432OUTSIDE WORK: SCOPE MOUNTEDDATE: 1-16-73FROM: BEIRCH AMMUNITION CORP.FIRED AMMO TYPE: TROCHESTER, N.Y.

& CONDITION: _____

GUN #: 375936PROOF: R.E.P.INSP.: 11TEST: 87CODE: ER = 10/68HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

CONSIDERABLE DIRT INCLUDING METAL PARTICLESINSIDE HOUSING. HARDENED LUBRICATION ON TRIGGER.CONNECTOR = 1.083 (1.080 MODEL DRAWING) TRIGGER = 1.076(1.076 MODEL DRAWING) SAFETY & TO CAM = .291 (.292 MODEL DRAWING)COMPLAINT: "FIRES WITH SAFETY ON"INCIDENT: FOLLOW DOWNCOMMENTS: THE CONNECTOR CAN WORK UP TO INTERFERE
WITH THE SEAR AND PREVENT RETRACTION INTO
COCKED POSITION.

EXHIBIT

23

PLAINTIFF'S
EXHIBIT

3179