

Carl Cuyler

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW R #: 003187

OUTSIDE WORK: NO DATE: 1-30-73

FROM: J. FOSTER

FIRE AMMO TYPE: - LYNCHBURG, VA.

& CONDITION: ASSEMBLER 97 GUN #: 6326074

PROOF: R.E.P. A INSP.: 9 TEST: 55 CODE: CT = 4/70

HEADING: O.K. GA./CAL.: 25-06

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR-TRIGGER CLEARANCE = 1.084 (MODEL 1.080) (DRAWING 1.083) TRIGGER.

CONNECTOR CLEARANCE = 1.072 (1.076) (1.070) CENTER LINE OF PIN HOLE

TO TOP OF TRIGGER = .974 (.973) (.971) CENTER OF PIVOT HOLE

IN SAFETY TO TOP OF CAM = .291 (.292) (.286)

COMPLAINT: "FIRED WITH SAFETY ON"

INCIDENT: FOLLOW DOWN

EXHIBIT

26

PLAINTIFF'S EXHIBIT

3177

COMMENTS: THE RIFLE WILL NOT FIRE WITH THE SAFETY ON.

THE CONDITIONS LISTED ABOVE: .005 TOO MUCH CLEAR-

ANCE BETWEEN CONNECTOR & TRIGGER, TOP OF TRIGGER

.001 OVER MAX. AND SAFETY .001 UNDER MIN., ALL

CONTRIBUTE TO AN INTERFERENCE BETWEEN THE

CONNECTOR AND SEAR WHICH WOULD PREVENT

RETRACTION INTO COCKED POSITION TO CAUSE FOLLOW

AL 0029707

DOWN.

171