

*File under safety*  
*Committee*  
**REMINGTON ARMS COMPANY, INC.**  
 INTER-DEPARTMENTAL CORRESPONDENCE  
*Remington*  


cc: R.L. Hall  
 C.B. Workman  
 W.E. Leek

*Tom*  
*Jim Barrett*  
**RECEIVED**  
 MAR 27 1975  
 E. G. LARSON

March 26, 1975

TO: E.G. LARSON  
 FROM: G.W. MARTIN

SUBJECT: MOHAWK 600'S AT CARTER'S IN HOUSTON, TEXAS

The safety was checked on a total of 354 rifles.

We used three (3) methods, as follows:

- A. Safety was placed in "mid" position, trigger was then pulled, and then the safety was released.
- B. Safety was placed in "mid" position, trigger was pulled, safety was then placed on safe, and the safety was next released.
- C. Safety was in fully on position, trigger pulled (very hard), and safety was released. \*Note: This check was not made on first five (5) guns - reason, Bill Carter was checking these.

Results:

Total guns unable to "trick".....	39
Total guns "tricked" by A or B. (above).....	154
Total guns "tricked" by both A and B .....	152
Total guns "tricked" by C.....	4
	<u>349</u>
	+ 5
	<u>354</u>

Grand total-315 rifles out of 354 could be tricked.

Codes for 350 rifles.

CU Apr. 71.....	23
KU May 71.....	2
AW Mar. 72.....	7
PX June 73.....	3
OX July 73.....	23
RX Nov. 73.....	43
XX Dec. 73.....	175
BY Jan. 74.....	31
CY Apr. 74.....	2
DY Sept. 74.....	<u>41</u>
	350

**RECEIVED**  
 MAR 31 1975  
 OFFICE - E. F. BARRETT

(continued)