

RECEIVING and ESTIMATE REPORT

ORDER R 22286

FROM DATE

RECEIVED

9/14/76

ESTIMATED

9/17/76

VIA

up

CHARGES

FROM

Peoria Police Dept

542 SW Adams St

Peoria, ILL

MODEL and GRADE

700 BDL variant

223 per

SERIAL NO.

A6237726

DATE

CODE

X2

12/1/75

FOR COMPUTER REFER. ONLY

GRADE
CODE

L1 sights

REPAIR CHG.

80 55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quota)

TOTAL

CUSTOMER'S COMPLAINT

Safety moved from safe to fire

Position

the weapon was in fire

MAIN FAULT

Trigger connector Broken

GALLERY REPORT

19461 - Trigger connector

DEMERIT
CODEFile - M/700 Customer
Complaints

(Clean) (Test) (Target)

Repairman

RECEIVING and ESTIMATE REPORT

ORDER R 22285

FROM DATE

RECEIVED

9-14-76

ESTIMATED

9/27/76

VIA

up

CHARGES

FROM

Peoria Police Dept

MODEL and GRADE

700 BDL variant 223 Rem

SERIAL NO.

A6236452

DATE CODE

X2

GRADE CODE

FOR COMPUTER REFER. ONLY

41 sights

REPAIR CHG.

\$55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quote)

TOTAL

CUSTOMER'S COMPLAINT

Safety mount from safe to fire position & hp weapon would fire

MAIN FAULT

connector Broken - Trigger AdS screws not properly AdS - outside of factory

GALLERY REPORT

DEMERIT CODE

19461 trigger connector

7461 - M/700
Customer Complaints

AdS trigger pull

(Clean) (Test) (Target)

Inspection

POLICE DEPARTMENT



Sept. 1, 1976

Remington Arms
Arms Service Division
Ilion, N.Y. 13357

Gentlemen:

Enclosed please find two Remingtons, Model 700, Varmint Special, .223 Cal.
rifles- Serial #'s A6237986 and A6236452. *R22286 R22285*

These rifles were purchased by this department earlier this year from the
Wammes Guns Inc., Belle Fontaine, Ohio. Both of these weapons were found to
be defective and when we contacted Wammes, we were informed to send the weapons
back to the manufacture as they would be the only ones who would take care of
them.

Both these weapons are used by our Tactical Unit, and we are in need of them
as soon as possible.

Both of these weapons were fired less than 100 rounds when it was found that
they were unsafe. With a live round in the chamber and the bolt closed, the
safety was moved from the "safe" to "fire" position the weapon would fire.
This did not happen every time, but it did happen intermittently.

Sincerely,

Russell Hawks
Sergeant Russell Hawks

542 SW Adams
Peoria, Illinois 61602
309/678-4521

R2507878