

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE



Approved Copies:

cc: K. D. Green
P. H. Holmberg

R. E. Fieltiz
C. A. Riley
K. D. Green
J. H. Chisnall
J. A. Stekl
R. L. St. John
P. H. Holmberg
W. H. Forson, Jr.
C. B. Workman
R. L. Sassone - For inclusion
in manual.

RECEIVED

SEP 15 1982

R. B. SPERLING

Bridgeport, Connecticut
September 13, 1982

R. B. SPERLING

RECALL INFORMATION IN FIELD SERVICE MANUAL

The Field Service Manual, which gives assembly, disassembly, and diagnostic information about our firearms, is being updated at this time. This manual is made available to our Recommended Gunsmiths and other gunsmiths who request it.

Previous editions of the manual have not had any reference to product recalls. For the following reasons, we propose to include Model 600 and XP-100 (attached) recall notes in the Field Service Manual:

- o Those guns which are capable of being "tricked" are dangerous and should be modified.
- o Four years after this recall was instituted, only 13% of the guns have been modified. Thus, there are still over 175,000 guns outstanding.
- o Because the recall was started several years ago, some dealers and gunsmiths have discarded the descriptions of the guns subject to recall. These inserts will provide them with a ready reference.
- o Recall was nationwide in scope as opposed to localized via a distribution pattern.


R. B. SPERLING

-2-

September 13, 1982

- o Many of our Recommended Gunsmiths were and are participating in the recall by making the repairs.

If you have no objection, we will have the XP-100 and Model 600 notices put in the Field Service Manual.


F. T. Millener

FTM:fms
att.