

Oct. 16, 1989

Mr. Kenneth Green, President
Remington Arms Co., Inc.

Dear Mr. Green,

Attached is my original letter to Remington concerning the quality of an ADL M-700, 3006 which I won in the NRA Pres. Firearms Sweepstakes. Please excuse the handwriting.

The letter deals with "little" things which indicate a lack of quality - wrong instruction booklet in box ie shotgun instead of ADL; very poor front sight alignment when the booklet states 100 yd factory alignment; poor "white dot" on front sight.

I also won a scope so the iron sights really are not a problem but I was considering using the rifle as is. To have the front sight aligned and the dot made uniform will cost me additional money, time and effort.

When cleaning my rifle the stock under the barrel and action is blistered (varnish) and rough as hell.

I own a dozen or so rifles/shotguns. I realize that there can be some "little" things straight from the box but my Ben 7600, Sako, Win, Ruger, Brownings all do not seem to have had sight or wood problems. I was writing primarily to suggest a tightening up of