

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660

GENERAL CONDITION: NEW R #: 006930

OUTSIDE WORK: SCOPE MOUNTED, SWIVELS ADDED. DATE: 3-13-72

CEMENT REMOVED-REAR ADJUSTING SCREW. FROM: ACKERMAN'S FIRST AID SUPPLIES

FIRE AMMO TYPE: - GROVE CITY, PA.

& CONDITION: _____ GUN #: 111373

PROOF: R.E.P. ^{ASSEMBLER 65} INSP.: 73 TEST: 79 CODE: KR = 5/68

HEADING: - GA./CAL.: 243 WIN.

BREACH OPENING: - CHECKED BY: PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR AND TOP INSIDE OF HOUSING COATED WITH DRIED LUBRICANT OR OTHER MATERIAL.

COMPLAINT: "GOES OFF WITHOUT WARNING."

INCIDENT: FOLLOW DOWN

COMMENTS: THE LUBRICANT OR WHATEVER, CAUSED SLUGGISH RESPONSE OF TRIGGER ASSEMBLY - TRIGGER FAILURE TO RETRACT, SEAR FAILURE TO RETURN TO COCKED POSITION.