

RECEIVING AND ESTIMATING REPORT

CUST NO: 051909 C.O.D		COMMENTS NO CORR	
CUSTOMER ORDER NO.			
DATE RECEIVED 0/24/91	DATE OPENED 10/29/91	DATE CODE 0A 7-80	SERIAL NUMBER B6244946
MODEL AND GRADE 700 30-06		BDL	
ACCESSORIES W/STUDS		SOFT CASE	
		ORDER R 91-21777	

FROM:	SHIP TO:
ADAMS, JOHN 1229 EAST 87TH ST BROOKLYN USA	ADAMS, JOHN 1229 EAST 87TH ST BROOKLYN USA
NY 11236	NY 11236

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11-4-91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	----------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *NO correspondence. "Pull trigger, would not fire; changing position of gun causes it to fire".*

MAIN FAULT: *Could not duplicate above complaint. However, disassembly of rifle revealed trigger assembly extremely dirty and contaminated with gummy residue. Trigger was not moving freely - rear safety pin sticking on trigger assembly with later improper maintenance. Trigger pull 5 1/2 pounds; rear lift was 5 1/2. Bolt stop gummed-up; not operating properly.*

REPAIRMAN: *Clean present trigger assembly if possible. If not, offer replacement trigger at 1/2 normal cost as a gesture of good-will.*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE