

Broadway Sports Center, Inc.

BROADWAY, VIRGINIA 22815

August 9, 1991

REMINGTON ARMS COMPANY, INC.
Arms Service Division
Ilion, NY 13357

Dear Sir or Madam:

The inclosed Remington Model 700 BDL, 30-06 Sprg. Serial Number: 6852122 is being returned because when pushing the safety from the safe to fire position the gun will sometimes fire accidentally.

This firearm was previously forwarded to Clark Brothers for repair of the same problem February 2, 1986. However customer has indicated that it does not appear that it was properly repaired as the same problem exists. The gun was not used for a 3 year period after it was supposedly repaired due to illness in the family.

Thanking you in advance.

Sincerely,

Clifford C. Corder
Broadway Sports Center, inc.
112 Mason Street
P.O. Box 576
Broadway, VA 22815-0576