

CEIVING AND ESTIMATING REPORT

R 93-07695

CUSTOMER ORDER NO.		ATTN: ROGER POTTER			
RECEIVED 11/93	DATE OPENED 03/10/93	DATE CODE KU 5-71	SERIAL NUMBER 6425422	NEW SERIAL NUMBER	MODEL AND GRADE 700 25-06 EOL
SORIES W7STUDS					

SHIP TO:

BROWNE, JAMES F. JR.
1401 PATRICIA #212
SAN ANTONIO

TX 78213

BROWNE, JAMES F. JR.
1401 PATRICIA #212
SAN ANTONIO

TX 78213

CUST NO: 076750 C.O.D L

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE
W					EXCISE
SLIGHTLY WORN					TAX
DRN					INSURANCE
RY WORN					UPS
REPAIRABLE					PARCEL POST
RRD					TOTAL

OWNER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
	A1	B1				
IER GROUP		B2			E1	F1
ASSY.		B3			E2	F2
EL ASSY.		B4		D1	E3	F3
ASSY.				D2	E4	F4
			C1	D3	E5	F5
			C2			

AULT

Upon receipt with inspection. Trigger will not engage, firing pin follows down when closing bolt. Examination revealed that all three (3) adjustment screws have been adjusted outside the factory. Factory adjustment removed. Top screw had not. Replaced complete trigger assembly at 1/2 normal replacement cost. In future if you will go ahead.

Ref. mfg 1971
Trigger Pull 3 lbs
Sensitivity .007

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92