

REIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-13175

INITIAL
FPS

CUSTOMER ORDER NO.

STAINLESS/CUSTOMER REMOVED BLUEING

DATE RECEIVED
04/14/98

DATE OPENED
04/15/98

DATE CODE
PU 6-71

SERIAL NUMBER
6445063

NEW SERIAL NUMBER

MODEL AND GRADE
700 17 REM

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION

NY 14411

SHIP TO:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION

NY
14411

CUST NO: 096024 C10.D

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Send quote

REPAIR CHARGE

20.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	R1				
TRIGGER GROUP						F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B5				F3
REC. ASSY.			D2	E4		F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mfg. 6-71 unable to duplicate customer concern as recd. Promptly put hand and customer adjusting screws were already outside of factory, see was gummy and sticking in housing. Exchange trigger assy. at special price as gesture of good will and to restore customer confidence in rifle.

PARTS

COMMENTS

*Trigger pull measured 4 1/2 to 6 # as recd. see left was 100
Bluing has been removed from bolt Assy*

REPAIRMAN

TAL

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/84