

Remington Arms
MayfieldQuality Manual 6-2
Appendix A
Form C-1036

First Article Inspection - Mayfield Results

Part Number

F 300466

Drawing #

C-300466

Part Name

LOCK PLUNGER

Rev. Level

A

Vendor

Isel,

Date Received

7/20/00

Lot #

SAMPLES

Average Min Max

#	Feature Name	#1	#2	#3	#4	#5	Average	Min	Max
1	$\phi .139 \pm .001$	.139	.139	.138	.138	.138	#DIV/0!	0.0000	0.0000
2	$\phi .060 \pm .002$	.059	.059	.059	.061	.060	#DIV/0!	0.0000	0.0000
3	$.042 \pm .005$	.043	.041	.042	.042	.042	#DIV/0!	0.0000	0.0000
4	$.160 \pm .003$	.159	.157	.158	.158	.160	#DIV/0!	0.0000	0.0000
5	R .015	.017	.017	.017	.017	.017	#DIV/0!	0.0000	0.0000
6	.005 x 45°	A	A	A	A	A	#DIV/0!	0.0000	0.0000
7	.005 x 45°	A	A	A	A	A	#DIV/0!	0.0000	0.0000
8	R .125 ± .003	.125	.126	.126	.125	.124	#DIV/0!	0.0000	0.0000
9	AISI 12L14	A	A	A	A	A	#DIV/0!	0.0000	0.0000
10	R15N 88-92	88.0	88.5	87.4	87.7	87.8	#DIV/0!	0.0000	0.0000
11	BLACK OXIDE	A	A	A	A	A	#DIV/0!	0.0000	0.0000
12							#DIV/0!	0.0000	0.0000
13							#DIV/0!	0.0000	0.0000
14							#DIV/0!	0.0000	0.0000
15							#DIV/0!	0.0000	0.0000
16							#DIV/0!	0.0000	0.0000
17							#DIV/0!	0.0000	0.0000
18							#DIV/0!	0.0000	0.0000
19							#DIV/0!	0.0000	0.0000
20							#DIV/0!	0.0000	0.0000
21							#DIV/0!	0.0000	0.0000
22							#DIV/0!	0.0000	0.0000
23							#DIV/0!	0.0000	0.0000
24							#DIV/0!	0.0000	0.0000
25							#DIV/0!	0.0000	0.0000
26							#DIV/0!	0.0000	0.0000
27							#DIV/0!	0.0000	0.0000
28							#DIV/0!	0.0000	0.0000
29							#DIV/0!	0.0000	0.0000
30							#DIV/0!	0.0000	0.0000

Inspected
Approved By
Rejected By

Date

7/25/00

Date

Revised By: M. Goelmboski
Revision Date: 2/14/00

First Article Inspection

ET06404