

MOO. 700  
Ser. No. A6647268  
Recd. 02-2-83  
Checked By RL Johnson  
Number           

R# 06332  
P.I. No  
MFD. 8-78

6-9-83

COMMENTS:

THIS GUN WAS COCKED, ITS SAFETY WAS SWITCH TO THE "S" POSITION, AND IT WAS PLACED INSIDE A COLD BOX (INSIDE THERMOMETER INDICATED -30F) AT 4:35 P.M. ON 06 APRIL 83.

UPON REMOVAL OF THIS GUN FROM THE COLD BOX (INSIDE THERMOMETER INDICATED -29F) AT 9:40 A.M. ON 07 APRIL 83, THE FOLLOWING TEST WAS IMMEDIATELY PERFORMED:

- ① Pull trigger to see if it binds or sticks back — IT DID NEITHER.
- ② Switch safety to "F" position — IT DID NOT FIRE-DOWN.
- ③ Open bolt and check for arrow — NONE
- ④ Close bolt and work safety — POSITIVE, SNAPPY ACTION.
- ⑤ Switch safety to "S" position, pull back hard on trigger, release trigger, switch safety to "F" position. Repeat this three times. — THE FIRING PIN DID NOT FIRE-DOWN.
- ⑥ With safety switched to "F" position, pull trigger. — THE FIRING PIN FIRED-DOWN. THE FIRST TIME IT FIRED-DOWN SLUGGISHLY AND SUBSEQUENT FIRE-DOWNS WERE SNAPPY.
- ⑦ Recock the bolt and repeat the entire test. — No PROBLEMS ENCOUNTERED AND NO F.S.R. OBSERVED.
- ⑧ Perform "trick test". — (GUN PASSED THE "TRICK TEST".

